



MOTOROLA

Microprocessor and Memory
Technologies Group

Order this document by
MC68SC302/D

MC68SC302

Errata and Added Information to **MC68SC302 Passive ISDN Protocol Engine** **User's Manual**

May 23, 1997

New items in *italics*

4.4.2 SERIAL INTERFACE MASK REGISTER (SIMASK)

On page 4-14, SIMASK description the SC302 UM says: "...The serial data strobes, SDS1 and SDS2 are asserted for the entire 8 bit time slot independent of the setting of the bits in the SIMASK register"

The UM should say: "...The serial data strobes, SDS1 and SDS2 are asserted for the bits which are set in the associated B channel mask, and negated for the bits which are cleared in the SIMASK register"

~~**4.5.3.2.3 Mixed Address EEPROM.**~~

~~On page 4-52, update "The 93C46 in the "by 8" organization is an example of this type of EEPROM" to:~~

~~The SGS-THOMSON 93C46A and the Xicor X25020 in the "by 8" organization are examples of this type of EEPROM.~~

5.4.1 Resource Data Layout in a Byte Serial Device

1. On page 5-7, change Table 5-3 Resource Data Layout as follows:

| ADDRESS | NAME | REGISTER-DESTINATION |
|---------|-------------------------|----------------------|
| 0x00-01 | Serial EEPROM Type/Mode | - |

This document contains information on a product under development. Motorola reserves the right to change or discontinue this product without notice.

SEMICONDUCTOR PRODUCT INFORMATION

| ADDRESS | NAME | REGISTER-DESTINATION |
|---------|--|----------------------|
| 0x02-03 | Reserved for future use. Must be programmed to 0 | - |
| 0x04 | Serial EEPROM Type | - |
| 0x05-06 | Reserved for future use. Must be programmed to 0 | - |
| 0x07 | Implementation Specific Information | 0x22 |
| 0x08 | First bye of Standard Resource Data | - |

2. On page 5-9, Figure 5-5. ISA-PNP Resource Data Layout in a Byte Serial EEPROM Device, the words “Serial Number” next to Byte 3 should be moved down one row so that they align with the words Byte 0.

5.4.3 I/O Configuration

On page 5-10, update the following items:

- Byte 0: I/O port descriptor tag (value = 01000111B = 0x47)
- Byte 1: Information byte: SC302 supports 16-bit address decoding, therefore bit 0 = 1, and bits 7 – 1 are reserved and must be 0 (value = 0x01).


5.4.4 Memory Configuration

On page 5-11, update the following items

- Byte 0: 10000001B = 0x81 (Memory Range Descriptor tag).
- Bytes 1-2: Length of the Memory Range Descriptor, bits[7:0] and bits [15:8] (values = 0x09 and 0x00, respectively, giving a length of 0x0009).
- Byte 3: 0_0_0_1_0_0_0_1= 0x11 (Information field: [Reserved]_[Not Expansion ROM]_[Not shadowable]_[8/16-bit supported]_[Decode support Range Length]_[Non-cachable]_[Writable]).

5.5 ISA-PNP CARD LEVEL CONTROL REGISTERS

1. On page 5-17, the ISI register, bit 5 has an error in the note. It should say “LOADED FROM 0x07 IN BYTE SERIAL DEVICE.”
2. On page 5-19, missing closing parentheses: Card Level (Vendor Defined)

Motorola reserves the right to make changes without further notice to any products herein. Motorola makes no warranty, representation or guarantee regarding the suitability of its products for any particular purpose, nor does Motorola assume any liability arising out of the application or use of any product or circuit, and specifically disclaims any and all liability, including without limitation consequential or incidental damages. "Typical" parameters can and do vary in different applications. All operating parameters, including "Typicals" must be validated for each customer application by customer's technical experts. Motorola does not convey any license under its patent rights nor the rights of others. Motorola products are not designed, intended, or authorized for use as components in systems intended for surgical implant into the body, or other applications intended to support or sustain life, or for any other application in which the failure of the Motorola product could create a situation where personal injury or death may occur. Should Buyer purchase or use Motorola products for any such unintended or unauthorized application, Buyer shall indemnify and hold Motorola and its officers, employees, subsidiaries, affiliates, and distributors harmless against all claims, costs, damages, and expenses, and reasonable attorney fees arising out of, directly or indirectly, any claim of personal injury or death associated with such unintended or unauthorized use, even if such claim alleges that Motorola was negligent regarding the design or manufacture of the part. Motorola and  are registered trademarks of Motorola, Inc. Motorola, Inc. is an Equal Opportunity/Affirmative Action Employer.

Literature Distribution Centers:

USA/EUROPE: Motorola Literature Distribution; P.O. Box 20912, Arizona 85036.

JAPAN: Nippon Motorola Ltd.; 4-32-1, Nishi-Gotanda, Shinagawa-ku, Tokyo 141 Japan.

ASIA-PACIFIC: Motorola Semiconductors H.K. Ltd.; Silicon Harbour Center, No. 2 Dai King Street, Tai Po Industrial Estate,