

2014 Mid-Year Product Discontinuation - 201406022DN
 NXP Semiconductor
 June 30, 2014

| Discontinued Orderable Part Number | Discontinued Part 12NC | Discontinued Part Number | Discontinued Part Description | Package Outline | Package Name | Discontinuation Type | Availability | Source | Last Time Buy Date | Last Time Delivery Date | Replacement Orderable Part# | Replacement part 12NC | Replacement Part Number | Replacement Part Description | Notes |
|------------------------------------|------------------------|--------------------------|---------------------------------------|-----------------|--------------|----------------------|----------------------|-------------------|--------------------|-------------------------|-----------------------------|-----------------------|-------------------------|------------------------------|--|
| BAP64-03/DG/B2/AX | 934067934115 | BAP64-03/DG/B2/A | PIN DIODE | SOD323 | SOD2 | Version Withdrawal | Limited | Customer Specific | 30-Sep-2014 | 31-Dec-2014 | BAP64-03,115 | 934055511115 | BAP64-03 | PIN DIODE | |
| BB173LXYL | 934067724315 | BB173LX | Varicap diode | SOD882D | SOD2 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | BB173X | 934067723115 | BB173 | Varicap diode | |
| BB174LXYL | 934067726315 | BB174LX | Varicap diode | SOD882D | SOD2 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | BB174X | 934067725115 | BB174 | Varicap diode | |
| BSH205,215 | 934054721215 | BSH205 | P-channel enhancement mode MOS trans. | SOT23 | TO-236AB | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | BSH205G2R | 934068496215 | BSH205G2 | small signal MOSFET | BSH205G2 in development; release Q1 2015 |
| BSS84AKT,115 | 934065307115 | BSS84AKT | small signal MOSFET | SOT416 | SC-75 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | BSS84AKM,315 | 934065309315 | BSS84AKM | small signal MOSFET | |
| BUK7514-55A,127 | 934055646127 | BUK7514-55A | 30V<-60V P CHANNEL TRENCHFET | SOT78A | SIL3P | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | BUK7514-60E,127 | 934066468127 | BUK7514-60E | AUTO Trench 6 (SOT78) | T6 Replacement |
| BUK753R1-40B,127 | 934057094127 | BUK753R1-40B | <=55V N CHANNEL TRENCHFET | SOT78A | SIL3P | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | BUK753R1-40E,127 | 934066424127 | BUK753R1-40E | AUTO Trench 6 (SOT78) | T6 Replacement |
| BUK764R3-40B,118 | 934057689118 | BUK764R3-40B | TRENCH 3 >25V | SOT404 | D2PAK | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | BUK764R0-40E,118 | 934066436118 | BUK764R0-40E | AUTO Trench 6 (SOT404) | T6 Replacement |
| BUK7609-55A,118 | 934057287118 | BUK7609-55A | 30V >-60V N CHANNEL GEN 2 TRE | SOT404 | D2PAK | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | BUK768R3-60E,118 | 934066644118 | BUK768R3-60E | AUTO Trench 6 (SOT404) | T6 Replacement |
| BUK7E11-55B,127 | 934058023127 | BUK7E11-55B | < 30V N CHANNEL TRENCHFET | SOT226 | I2PAK | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | BUK7E13-60E,127 | 934066633127 | BUK7E13-60E | AUTO Trench 6 (SOT226) | T6 Replacement |
| BUK7Y54-75B,115 | 934063304115 | BUK7Y54-75B | 9603 AUTO TRENCH 3 | SOT669 | LFPAK | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | BUK7Y41-80EX | 934067424115 | BUK7Y41-80E | AUTO Trench 6 (SOT669) | T6 Replacement |
| BUK7Y35-55B,115 | 934063327115 | BUK7Y35-55B | 9603 AUTO TRENCH 3 | SOT669 | LFPAK | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | BUK7Y43-60EX | 934067482115 | BUK7Y43-60E | AUTO Trench 6 (SOT669) | T6 Replacement |
| BUK954R4-80E,127 | 934066523127 | BUK954R4-80E | AUTO Trench 6 (SOT78) | SOT78A | SIL3P | Full Withdrawal | Limited | Multiple | 30-Sep-2014 | 31-Mar-2015 | BUK9506-75B,127 | 934057111127 | BUK9506-75B | 75V N CHANNEL TRFT | Not included in product transfer from Global Foundries |
| BUK958R5-40E,127 | 934066422127 | BUK958R5-40E | AUTO Trench 6 (SOT78) | SOT78A | SIL3P | Full Withdrawal | Limited | Multiple | 30-Sep-2014 | 31-Mar-2015 | BUK9509-40B,127 | 934057696127 | BUK9509-40B | TRENCH 3 >25V | Not included in product transfer from Global Foundries |
| BUK9516-55A,127 | 934056022127 | BUK9516-55A | 30V<-60V P CHANNEL GEN 2 TRE | SOT78A | SIL3P | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | BUK9515-60E,127 | 934066475127 | BUK9515-60E | AUTO Trench 6 (SOT78) | T6 Replacement |
| BUK953R2-40E,127 | 934066421127 | BUK953R2-40E | AUTO Trench 6 (SOT78) | SOT78A | SIL3P | Full Withdrawal | Limited | Multiple | 30-Sep-2014 | 31-Mar-2015 | BUK953R2-40B,127 | 934057096127 | BUK953R2-40B | <=55V N CHANNEL TRENCHFET | Not included in product transfer from Global Foundries |
| BUK952R3-40E,127 | 934066419127 | BUK952R3-40E | AUTO Trench 6 (SOT78) | SOT78A | SIL3P | Full Withdrawal | Limited | Multiple | 30-Sep-2014 | 31-Mar-2015 | BUK953R2-40B,127 | 934057096127 | BUK953R2-40B | <=55V N CHANNEL TRENCHFET | Not included in product transfer from Global Foundries |
| BUK9618-55A,118 | 934056812118 | BUK9618-55A | 30V>-60V N CHANNEL GEN 2 TRE | SOT404 | D2PAK | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | BUK9614-60E,118 | 934066637118 | BUK9614-60E | AUTO Trench 6 (SOT404) | T6 Replacement |
| BUK961R7-40E,118 | 934066439118 | BUK961R7-40E | AUTO Trench 6 (SOT404) | SOT404 | D2PAK | Full Withdrawal | Limited | Multiple | 30-Sep-2014 | 31-Mar-2015 | BUK961R6-40E,118 | 934066507118 | BUK961R6-40E | AUTO Trench 6 (SOT404) | Not included in product transfer from Global Foundries |
| BUK9610-55A,118 | 934056852118 | BUK9610-55A | 30V>-60V N CHANNEL GEN 2 TRE | SOT404 | D2PAK | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | BUK969R0-60E,118 | 934066636118 | BUK969R0-60E | AUTO Trench 6 (SOT404) | T6 Replacement |
| BUK9611-55A,118 | 934055880118 | BUK9611-55A | 30V>-60V N CHANNEL TRANCHFET | SOT404 | D2PAK | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | BUK969R0-60E,118 | 934066636118 | BUK969R0-60E | AUTO Trench 6 (SOT404) | T6 Replacement |
| BUK9609-55A,118 | 934057019118 | BUK9609-55A | 30V >-60V N CHANNEL GEN 2 TRE | SOT404 | D2PAK | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | BUK969R0-60E,118 | 934066636118 | BUK969R0-60E | AUTO Trench 6 (SOT404) | T6 Replacement |
| BUK9E4R9-60E,127 | 934066657127 | BUK9E4R9-60E | AUTO Trench 6 (SOT226) | SOT226 | I2PAK | Full Withdrawal | Non-Manufacturabl e | Multiple | 30-Jun-2014 | 30-Jun-2014 | BUK9E06-55B,127 | 934057313127 | BUK9E06-55B | <=55V N CHANNEL TRENCHFET | Not included in product transfer from Global Foundries |
| HT2DC20S20/F,122 | 935233940122 | HT2DC20S20/F | HITAG | SOT385-1 | PLLMC | Version Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | HT2DC20S20/F/RS/P | 935303132122 | HT2DC20S20/F/R | HITAG | Restart of SNR range. Replacement part available. Contact your local NXP sales office. |
| HT2ICS2002W/V6F,00 | 935294195005 | HT2ICS2002W/V6F | HITAG | | UNCASED | Version Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | HT2ICS2002W/V6F/RV | 935303128005 | HT2ICS2002W/V6F/R | HITAG | Restart of SNR range. Replacement part available. Contact your local NXP sales office. |
| HT2ICS2002W/V6F,00 | 935294195003 | HT2ICS2002W/V6F | HITAG | | UNCASED | Version Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | HT2ICS2002W/V6F/RZ | 935303128003 | HT2ICS2002W/V6F/R | HITAG | Restart of SNR range. Replacement part available. Contact your local NXP sales office. |
| HT2MOA2S20/E/3/RJ | 935303129118 | HT2MOA2S20/E/3/R | HITAG | SOT500-1 | PLLMC | Version Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | HT2MOA4S20/E/3/R/J | 935303945118 | HT2MOA4S20/E/3/R | HITAG | Restart of SNR range. Replacement part available. Contact your local NXP sales office. |
| HTCICC6401EW/C7,00 | 935294192005 | HTCICC6401EW/C7 | HITAG | | UNCASED | Version Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | HTCICC6402FUG/A/M,0 | 935288701005 | HTCICC6402FUG/A/M | HITAG | Replacement part available. Contact your local NXP sales office. |
| HTCICC6401EW/C7,00 | 935294192003 | HTCICC6401EW/C7 | HITAG | | UNCASED | Version Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | HTCICC6402FUG/A/M,0 | 935288701005 | HTCICC6402FUG/A/M | HITAG | Replacement part available. Contact your local NXP sales office. |
| HTMS1001FTB/AF,115 | 935289811115 | HTMS1001FTB/AF | HITAG | SOT1122 | XSON3 | Version Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | HTMS8001FTB/AF,15 | 935290071115 | HTMS8001FTB/AF | HITAG | Replacement 280pF version. Contact your local NXP sales office. |
| HTMS1001FTK/AF,115 | 935290131115 | HTMS1001FTK/AF | HITAG | SOT899-1 | HVSON2 | Version Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | HTMS8001FTK/AF,15 | 935290135115 | HTMS8001FTK/AF | HITAG | Replacement 280pF version. Contact your local NXP sales office. |
| HTMS1101FTB/AF,115 | 935290066115 | HTMS1101FTB/AF | HITAG | SOT1122 | XSON3 | Version Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | HTMS8101FTB/AF,15 | 935290072115 | HTMS8101FTB/AF | HITAG | Replacement 280pF version. Contact your local NXP sales office. |

2014 Mid-Year Product Discontinuation - 201406022DN
 NXP Semiconductor
 June 30, 2014

| | | | | | | | | | | | | | | | |
|--------------------|--------------|----------------|----------------------------|----------|----------|--------------------|----------------------|----------|-------------|-------------|--------------------|--------------|-----------------|------------------------|--|
| HTMS1101FTK/AF,115 | 935290132115 | HTMS1101FTK/AF | HITAG | SOT899-1 | HVSON2 | Version Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | HTMS8101FTK/AF,15 | 935290136115 | HTMS8101FTK/AF | HITAG | Replacement 280pF version. Contact your local NXP sales office. |
| HTMS1101FUG/AM,005 | 935288703005 | HTMS1101FUG/AM | HITAG | | UNCASED | Version Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | HTMS8101FUG/AM,005 | 935288711005 | HTMS8101FUG/AM | HITAG | Replacement 280pF version. Contact your local NXP sales office. |
| HTMS1201FTB/AF,115 | 935290067115 | HTMS1201FTB/AF | HITAG | SOT1122 | XSON3 | Version Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | HTMS8201FTB/AF,15 | 935290073115 | HTMS8201FTB/AF | HITAG | Replacement 280pF version. Contact your local NXP sales office. |
| HTMS1201FTK/AF,115 | 935290133115 | HTMS1201FTK/AF | HITAG | SOT899-1 | HVSON2 | Version Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | HTMS8201FTK/AF,15 | 935290137115 | HTMS8201FTK/AF | HITAG | Replacement 280pF version. Contact your local NXP sales office. |
| HTMS1201FUG/AM,005 | 935288704005 | HTMS1201FUG/AM | HITAG | | UNCASED | Version Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | HTMS8201FUG/AM,005 | 935288712005 | HTMS8201FUG/AM | HITAG | Replacement 280pF version. Contact your local NXP sales office. |
| IP4855CX25/P,135 | 934065237135 | IP4855CX25/P | Active IDs & ESD & EMI | | NONE | Version Withdrawal | Limited | Multiple | 31-Dec-2014 | 30-Jun-2015 | IP4855CX25Z | 934065061014 | IP4855CX25 | Active IDs & ESD & EMI | Contact Marketing for Replacement Part. |
| MF1S2000XDA4,118 | 935293826118 | MF1S2000XDA4 | MIFARE | SOT500-2 | PLLMC | Version Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | MF1S2000XDA4/V1 | 935302819118 | MF1S2000XDA4/V1 | MIFARE | Replacement part available. Contact your local NXP sales office. |
| MF1S5031XDUF,005 | 935293808005 | MF1S5031XDUF | MIFARE | | UNCASED | Version Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | MF1S5031XDUF/V1 | 935302803005 | MF1S5031XDUF/V1 | MIFARE | Replacement part available. Contact your local NXP sales office. |
| MF1S2000XDA8,118 | 935293841118 | MF1S2000XDA8 | MIFARE | SOT500-4 | PLLMC | Version Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | MF1S2000XDA8/V1 | 935302826118 | MF1S2000XDA8/V1 | MIFARE | Replacement part available. Contact your local NXP sales office. |
| MF1S2001XDUF,005 | 935293809005 | MF1S2001XDUF | MIFARE | | UNCASED | Version Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | MF1S2001XDUF/V1 | 935302806005 | MF1S2001XDUF/V1 | MIFARE | Replacement part available. Contact your local NXP sales office. |
| MF1S2030XDA4,118 | 935293827118 | MF1S2030XDA4 | MIFARE | SOT500-2 | PLLMC | Version Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | MF1S2030XDA4/V1 | 935302821118 | MF1S2030XDA4/V1 | MIFARE | Replacement part available. Contact your local NXP sales office. |
| MF1S2030XDA8,118 | 935293842118 | MF1S2030XDA8 | MIFARE | SOT500-4 | PLLMC | Version Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | MF1S2030XDA8/V1 | 935302827118 | MF1S2030XDA8/V1 | MIFARE | Replacement part available. Contact your local NXP sales office. |
| MF1S2031XDUD,005 | 935293804005 | MF1S2031XDUD | MIFARE | | UNCASED | Version Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | MF1S2031XDUD/V1 | 935302808005 | MF1S2031XDUD/V1 | MIFARE | Replacement part available. Contact your local NXP sales office. |
| MF1S2031XDUF,005 | 935293811005 | MF1S2031XDUF | MIFARE | | UNCASED | Version Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | MF1S2031XDUF/V1 | 935302809005 | MF1S2031XDUF/V1 | MIFARE | Replacement part available. Contact your local NXP sales office. |
| MF1S5000XDA4,118 | 935293824118 | MF1S5000XDA4 | MIFARE | SOT500-2 | PLLMC | Version Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | MF1S5000XDA4/V1 | 935302816118 | MF1S5000XDA4/V1 | MIFARE | Replacement part available. Contact your local NXP sales office. |
| MF1S5000XDA8,118 | 935293838118 | MF1S5000XDA8 | MIFARE | SOT500-4 | PLLMC | Version Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | MF1S5000XDA8/V1 | 935302824118 | MF1S5000XDA8/V1 | MIFARE | Replacement part available. Contact your local NXP sales office. |
| MF1S5001XDUD,005 | 935293802005 | MF1S5001XDUD | MIFARE | | UNCASED | Version Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | MF1S5001XDUD/V1 | 935302799005 | MF1S5001XDUD/V1 | MIFARE | Replacement part available. Contact your local NXP sales office. |
| MF1S5001XDUF,005 | 935293807005 | MF1S5001XDUF | MIFARE | | UNCASED | Version Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | MF1S5001XDUF/V1 | 935302801005 | MF1S5001XDUF/V1 | MIFARE | Replacement part available. Contact your local NXP sales office. |
| MF1S5030XDA4,118 | 935293825118 | MF1S5030XDA4 | MIFARE | SOT500-2 | PLLMC | Version Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | MF1S5030XDA4/V1 | 935302818118 | MF1S5030XDA4/V1 | MIFARE | Replacement part available. Contact your local NXP sales office. |
| MF1S5030XDA8,118 | 935293839118 | MF1S5030XDA8 | MIFARE | SOT500-4 | PLLMC | Version Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | MF1S5030XDA8/V1 | 935302825118 | MF1S5030XDA8/V1 | MIFARE | Replacement part available. Contact your local NXP sales office. |
| MF1S5031XDUD,005 | 935293792005 | MF1S5031XDUD | MIFARE | | UNCASED | Version Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | MF1S5031XDUD/V1 | 935302802005 | MF1S5031XDUD/V1 | MIFARE | Replacement part available. Contact your local NXP sales office. |
| MF1S7000XDA4,118 | 935293828118 | MF1S7000XDA4 | MIFARE | SOT500-2 | PLLMC | Version Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | MF1S7000XDA4/V1 | 935302822118 | MF1S7000XDA4/V1 | MIFARE | Replacement part available. Contact your local NXP sales office. |
| MF1S7000XDA8,118 | 935293844118 | MF1S7000XDA8 | MIFARE | SOT500-4 | PLLMC | Version Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | MF1S7000XDA8/V1 | 935302828118 | MF1S7000XDA8/V1 | MIFARE | Replacement part available. Contact your local NXP sales office. |
| MF1S7001XDUD,005 | 935293805005 | MF1S7001XDUD | MIFARE | | UNCASED | Version Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | MF1S7001XDUD/V1 | 935302812005 | MF1S7001XDUD/V1 | MIFARE | Replacement part available. Contact your local NXP sales office. |
| MF1S7001XDUF,005 | 935293812005 | MF1S7001XDUF | MIFARE | | UNCASED | Version Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | MF1S7001XDUF/V1 | 935302813005 | MF1S7001XDUF/V1 | MIFARE | Replacement part available. Contact your local NXP sales office. |
| MF1S7030XDA4,118 | 935293829118 | MF1S7030XDA4 | MIFARE | SOT500-2 | PLLMC | Version Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | MF1S7030XDA4/V1 | 935302823118 | MF1S7030XDA4/V1 | MIFARE | Replacement part available. Contact your local NXP sales office. |
| MF1S7030XDA8,118 | 935293845118 | MF1S7030XDA8 | MIFARE | SOT500-4 | PLLMC | Version Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | MF1S7030XDA8/V1 | 935302829118 | MF1S7030XDA8/V1 | MIFARE | Replacement part available. Contact your local NXP sales office. |
| MF1S7031XDUD,005 | 935293806005 | MF1S7031XDUD | MIFARE | | UNCASED | Version Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | MF1S7031XDUD/V1 | 935302814005 | MF1S7031XDUD/V1 | MIFARE | Replacement part available. Contact your local NXP sales office. |
| MF1S7031XDUF,005 | 935293813005 | MF1S7031XDUF | MIFARE | | UNCASED | Version Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | MF1S7031XDUF/V1 | 935302815005 | MF1S7031XDUF/V1 | MIFARE | Replacement part available. Contact your local NXP sales office. |
| NT2H0301GODUD,005 | 935297045005 | NT2H0301GODUD | NFC Tags | | UNCASED | Version Withdrawal | Standard End Of Life | Sole | 31-Mar-2015 | 30-Jun-2015 | NT2H1311GODUDV | 935299912005 | NT2H1311GODUD | NFC Tags | Contact your local NXP sales office for replacement. |
| 2N7002K,215 | 934057974215 | 2N7002K | 60V GEN 2 N-CHANNEL TRENCH | SOT23 | TO-236AB | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | NX7002AK,215 | 934066291215 | NX7002AK | small signal MOSFET | |
| PMF3800SN,115 | 934058527115 | PMF3800SN | 60V N CHANNEL TRENCHFET | SOT323 | SC-70 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | NX7002BKR | 934068055215 | NX7002BK | small signal MOSFET | Replacement: NX7002BKW (release Sept 2014) |
| PBL1501V,115 | 934058047115 | PBL1501V | Loadswitch | SOT666 | SOT6 | Full Withdrawal | Standard End Of Life | Sole | 31-Mar-2015 | 30-Jun-2015 | PBL1501Y,115 | 934058052115 | PBL1501Y | Loadswitch | Replacement PBL1501Y |
| PBL1502V,115 | 934058048115 | PBL1502V | Loadswitch | SOT666 | SOT6 | Full Withdrawal | Standard End Of Life | Sole | 31-Mar-2015 | 30-Jun-2015 | PBL1502Y,115 | 934058053115 | PBL1502Y | Loadswitch | Replacement PBL1502Y |
| PBL1503V,115 | 934058049115 | PBL1503V | Loadswitch | SOT666 | SOT6 | Full Withdrawal | Standard End Of Life | Sole | 31-Mar-2015 | 30-Jun-2015 | PBL1503Y,115 | 934058054115 | PBL1503Y | Loadswitch | Replacement PBL1503Y |
| PBL1504V,115 | 934058051115 | PBL1504V | Loadswitch | SOT666 | SOT6 | Full Withdrawal | Standard End Of Life | Sole | 31-Mar-2015 | 30-Jun-2015 | PBL1504Y,115 | 934058055115 | PBL1504Y | Loadswitch | Replacement PBL1504Y |
| PBL2001S,115 | 934060277115 | PBL2001S | Loadswitch | SOT96-1 | SO8 | Full Withdrawal | Standard End Of Life | Sole | 31-Mar-2015 | 30-Jun-2015 | PBL2021D,115 | 934061573115 | PBL2021D | COMPLEX DISCRETES | Replacement PBL2021D |

2014 Mid-Year Product Discontinuation - 201406022DN
 NXP Semiconductor
 June 30, 2014

| | | | | | | | | | | | | | | | |
|--------------------|--------------|------------------|----------------------------|----------|----------|--------------------|----------------------|----------|-------------|-------------|--------------------|--------------|-------------------|----------------------------|--|
| PBLS2002S,115 | 934060278115 | PBLS2002S | Loadswitch | SOT96-1 | SO8 | Full Withdrawal | Standard End Of Life | Sole | 31-Mar-2015 | 30-Jun-2015 | PBLS2022D,115 | 934061574115 | PBLS2022D | COMPLEX DISCRETES | Replacement PBLS2022D |
| PBLS2003S,115 | 934060279115 | PBLS2003S | Loadswitch | SOT96-1 | SO8 | Full Withdrawal | Standard End Of Life | Sole | 31-Mar-2015 | 30-Jun-2015 | PBLS2023D,115 | 934061575115 | PBLS2023D | COMPLEX DISCRETES | Replacement PBLS2023D |
| PBLS4001V,115 | 934058632115 | PBLS4001V | Loadswitch | SOT666 | SOT6 | Full Withdrawal | Standard End Of Life | Sole | 31-Mar-2015 | 30-Jun-2015 | PBLS4001Y,115 | 934058644115 | PBLS4001Y | Loadswitch | Replacement PBLS4001Y |
| PBLS4002V,115 | 934058633115 | PBLS4002V | Loadswitch | SOT666 | SOT6 | Full Withdrawal | Standard End Of Life | Sole | 31-Mar-2015 | 30-Jun-2015 | PBLS4002Y,115 | 934058645115 | PBLS4002Y | Loadswitch | Replacement PBLS4002Y |
| PBLS4003V,115 | 934058634115 | PBLS4003V | Loadswitch | SOT666 | SOT6 | Full Withdrawal | Standard End Of Life | Sole | 31-Mar-2015 | 30-Jun-2015 | PBLS4003Y,115 | 934058646115 | PBLS4003Y | Loadswitch | Replacement PBLS4003Y |
| PBLS4004V,115 | 934058635115 | PBLS4004V | Loadswitch | SOT666 | SOT6 | Full Withdrawal | Standard End Of Life | Sole | 31-Mar-2015 | 30-Jun-2015 | PBLS4004Y,115 | 934058647115 | PBLS4004Y | Loadswitch | Replacement PBLS4004Y |
| PBLS4005V,115 | 934058636115 | PBLS4005V | Loadswitch | SOT666 | SOT6 | Full Withdrawal | Standard End Of Life | Sole | 31-Mar-2015 | 30-Jun-2015 | PBLS4005Y,115 | 934058648115 | PBLS4005Y | Loadswitch | Replacement PBLS4005Y |
| PBSS4140V,115 | 934056508115 | PBSS4140V | BISS | SOT666 | SOT6 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | PBSS4160T,215 | 934057667215 | PBSS4160T | BISS | Replacement PBSS4160T |
| PBSS5140V,315 | 934056817315 | PBSS5140V | BISS | SOT666 | SOT6 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | PBSS5160T,215 | 934057668215 | PBSS5160T | BISS | Replacement pbss5160T |
| PBSS5140V,115 | 934056817115 | PBSS5140V | BISS | SOT666 | SOT6 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | PBSS5160T,215 | 934057668215 | PBSS5160T | BISS | Replacement pbss5160T |
| PCA2001CX8/5/1,025 | 935286823025 | PCA2001CX8/5/1 | WATCH CIRCUIT, SOLDERBUMPS | | UNCASED | Version Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | PCA2001U/10AC/1,00 | 935289559005 | PCA2001U/10A C/1 | CLOCKS AND WATCHES | Only this variant is discontinued |
| PCA85132U/2DB/Q1,0 | 935290543026 | PCA85132U/2DB/Q1 | LCD segment driver 4 x160 | | UNCASED | Version Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | PCA85132U/2DA/Q1,0 | 935290542026 | PCA85132U/2D A/Q1 | LCD segment driver 4 x160 | Replacement part with hard bumps. |
| PCA85133U/2DB/Q1,0 | 935290457026 | PCA85133U/2DB/Q1 | LCD Segment driver 4x80 V3 | | UNCASED | Version Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | PCA85133U/2DA/Q1 Z | 935290456033 | PCA85133U/2D A/Q1 | LCD Segment driver 4x80 V3 | Replacement part with hard bumps. |
| PCF2113WU/2/F4,026 | 935267486026 | PCF2113WU/2/F4 | DISPLAY DRIVERS | | UNCASED | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | PCF2113EU/2/F4,026 | 935264034026 | PCF2113EU/2F 4 | DISPLAY DRIVERS | |
| PCF2123U/5GA/1,015 | 935295429015 | PCF2123U/5GA/1 | RTC SPI FFC | | UNCASED | Version Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | PCF2123U/12HA/1,0 | 935292966005 | PCF2123U/12HA /1 | RTC SPI FFC | Only this variant is discontinued |
| PCF8885T/1,518 | 935296169518 | PCF8885T/1 | 8 channel touch switch | | SO28 | Version Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | PCF8885TS/1,118 | 935296171118 | PCF8885TS/1 | 8 channel touch switch | Only this variant is discontinued |
| PEM12STD/WT,115 | 934064086115 | PEM12STD/WT | ESD & EMI | SOT665 | SOT5 | Full Withdrawal | Limited | Multiple | 31-Dec-2014 | 30-Jun-2015 | PEM12STD/HT,115 | 934064083115 | PEM12STD/HT | ESD & EMI | Contact Marketing for Replacement Part. |
| PESD12VS2UAT,215 | 934058064215 | PESD12VS2UAT | Protection diode | SOT23 | TO-236AB | Full Withdrawal | Limited | Multiple | 31-Dec-2014 | 30-Jun-2015 | PESD12VS2UT,215 | 934057610215 | PESD12VS2UT | Protection diode | Replacement part PESD12VS2UT |
| PESD12VS4UD,115 | 934059303115 | PESD12VS4UD | Protection diode | SOT457 | SC-74 | Full Withdrawal | Limited | Multiple | 31-Dec-2014 | 30-Jun-2015 | PESD12VS5UD,115 | 934058434115 | PESD12VS5UD | Protection diode | Replacement part PESD12VS5UD |
| PESD15VS4UD,115 | 934059304115 | PESD15VS4UD | Protection diode | SOT457 | SC-74 | Full Withdrawal | Limited | Multiple | 31-Dec-2014 | 30-Jun-2015 | PESD15VS5UD,115 | 934058435115 | PESD15VS5UD | Protection diode | Replacement part PESD15VS5UD |
| PESD3V3V4UF,115 | 934061197115 | PESD3V3V4UF | Protection diode | SOT886 | XSON6 | Full Withdrawal | Limited | Multiple | 31-Dec-2014 | 30-Jun-2015 | PESD3V3L4UF,115 | 934061194115 | PESD3V3L4UF | Protection diode | Replacement part PESD3V3L4UF |
| BZA862AL,115 | 934056984115 | BZA862AL | Protection diode | SOT353 | UMT5 | Full Withdrawal | Limited | Multiple | 31-Dec-2014 | 30-Jun-2015 | PESD3V3L4UG,115 | 934057784115 | PESD3V3L4UG | Protection diode | Replacement part PESD3V3L4UG |
| BZA868AL,115 | 934056985115 | BZA868AL | Protection diode | SOT353 | UMT5 | Full Withdrawal | Limited | Multiple | 31-Dec-2014 | 30-Jun-2015 | PESD3V3L4UG,115 | 934057784115 | PESD3V3L4UG | Protection diode | Replacement part PESD3V3L4UG |
| BZA868A,115 | 934056045115 | BZA868A | Protection diode | SOT353 | UMT5 | Full Withdrawal | Limited | Multiple | 31-Dec-2014 | 30-Jun-2015 | PESD3V3L4UG,115 | 934057784115 | PESD3V3L4UG | Protection diode | Replacement part PESD3V3L4UG |
| PESD3V3V4UG,115 | 934058733115 | PESD3V3V4UG | Protection diode | SOT353 | UMT5 | Full Withdrawal | Limited | Multiple | 31-Dec-2014 | 30-Jun-2015 | PESD3V3L4UG,115 | 934057784115 | PESD3V3L4UG | Protection diode | Replacement part PESD3V3L4UG |
| BZA862AVL,115 | 934057259115 | BZA862AVL | Protection diode | SOT353 | UMT5 | Full Withdrawal | Limited | Multiple | 31-Dec-2014 | 30-Jun-2015 | PESD3V3L4UG,115 | 934057784115 | PESD3V3L4UG | Protection diode | Replacement part PESD3V3L4UG |
| BZA862A,115 | 934056043115 | BZA862A | Protection diode | SOT353 | UMT5 | Full Withdrawal | Limited | Multiple | 31-Dec-2014 | 30-Jun-2015 | PESD3V3L4UG,115 | 934057784115 | PESD3V3L4UG | Protection diode | Replacement part PESD3V3L4UG |
| BZA856AL,115 | 934056983115 | BZA856AL | Protection diode | SOT353 | UMT5 | Full Withdrawal | Limited | Multiple | 31-Dec-2014 | 30-Jun-2015 | PESD3V3L4UG,115 | 934057784115 | PESD3V3L4UG | Protection diode | Replacement part PESD3V3L4UG |
| BZA956AVL,115 | 934057489115 | BZA956AVL | Protection diode | SOT665 | SOT5 | Full Withdrawal | Limited | Multiple | 31-Dec-2014 | 30-Jun-2015 | PESD3V3L4UW,115 | 934057791115 | PESD3V3L4UW | Protection diode | Replacement part PESD3V3L4UW |
| BZA968AVL,115 | 934057299115 | BZA968AVL | Protection diode | SOT665 | SOT5 | Full Withdrawal | Limited | Multiple | 31-Dec-2014 | 30-Jun-2015 | PESD3V3L4UW,115 | 934057791115 | PESD3V3L4UW | Protection diode | Replacement part PESD3V3L4UW |
| PESD3V3L1UA,115 | 934063223115 | PESD3V3L1UA | Protection Diode | SOD323 | SOD2 | Full Withdrawal | Limited | Multiple | 31-Dec-2014 | 30-Jun-2015 | PESD5V0L1UA,115 | 934063222115 | PESD5V0L1UA | Protection Diode | Replacement part PESD5V0L1UA |
| PESD9X5.0L,315 | 934065228315 | PESD9X5.0L | Protection Diode | SOD882 | SOD2 | Full Withdrawal | Limited | Multiple | 31-Dec-2014 | 30-Jun-2015 | PESD5V0L1UL,315 | 934062738315 | PESD5V0L1UL | Protection Diode | Replacement part PESD5V0L1UL |
| PESD5V0V4UF,115 | 934061202115 | PESD5V0V4UF | Protection diode | SOT886 | XSON6 | Full Withdrawal | Limited | Multiple | 31-Dec-2014 | 30-Jun-2015 | PESD5V0L4UF,115 | 934061198115 | PESD5V0L4UF | Protection diode | Replacement part PESD5V0L4UF |
| PESD5V0V4UG,115 | 934058734115 | PESD5V0V4UG | Protection diode | SOT353 | UMT5 | Full Withdrawal | Limited | Multiple | 31-Dec-2014 | 30-Jun-2015 | PESD5V0L4UG,115 | 934057785115 | PESD5V0L4UG | Protection diode | Replacement part PESD5V0L4UG |
| PJF7992ATW/C1C,518 | 935288267518 | PJF7992ATW/C1C | READER CHIPS | SOT527-1 | HTSSOP20 | Version Withdrawal | Standard End Of Life | Sole | 31-Mar-2015 | 30-Jun-2015 | PJF7992ATW/C1C/DJ | 935299904118 | PJF7992ATW/C1C/D | READER CHIPS | Pls. refer to PCN 201312005F01, pls contact Marketing for replacement. |
| PJF7993ATW/C1C,518 | 935288603518 | PJF7993ATW/C1C | ABIC | SOT527-1 | HTSSOP20 | Version Withdrawal | Standard End Of Life | Sole | 31-Mar-2015 | 30-Jun-2015 | PJF7993ATW/C1C/DJ | 935302174118 | PJF7993ATW/C1C/D | ABIC | Pls. refer to PCN 201312005F01, pls contact Marketing for replacement. |
| PMDPB28UN,115 | 934066488115 | PMDPB28UN | small signal MOSFET | SOT1118 | HUSON6 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | PMDPB30XN,115 | 934066581115 | PMDPB30XN | small signal MOSFET | |

2014 Mid-Year Product Discontinuation - 201406022DN
 NXP Semiconductor
 June 30, 2014

| | | | | | | | | | | | | | | | |
|--------------------|--------------|-----------------|---------------------------|----------|----------|--------------------|----------------------|----------|-------------|-------------|------------------|--------------|-----------------|----------------------------------|--|
| IP4306CX2/A,315 | 934063618315 | IP4306CX2/A | ESD PROTECTION | | NONE | Full Withdrawal | Limited | Multiple | 31-Dec-2014 | 30-Jun-2015 | PMEG2002AESF,315 | 934065236315 | PMEG2002AESF | ESD Protection | Contact Marketing for Replacement Part. |
| PMGD175XN,115 | 934066754115 | PMGD175XN | small signal MOSFET | SOT363 | SC-88 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | PMGD175XNEX | 934068835115 | PMGD175XNE | small signal MOSFET | PMGD175XNE in development; release Q2 2015 |
| PMPB12UN,115 | 934066861115 | PMPB12UN | small signal MOSFET | SOT1220 | SOT1220 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | PMPB10XNE,115 | 934066863115 | PMPB10XNE | small signal MOSFET | |
| PMPB20UN,115 | 934066862115 | PMPB20UN | small signal MOSFET | SOT1220 | SOT1220 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | PMPB23XNE,115 | 934066865115 | PMPB23XNE | small signal MOSFET | |
| PMV22EN,215 | 934065651215 | PMV22EN | small signal MOSFET | SOT23 | TO-236AB | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | PMV20ENR | 934068497215 | PMV20EN | small signal MOSFET | |
| PMV28UN,215 | 934065644215 | PMV28UN | small signal MOSFET | SOT23 | TO-236AB | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | PMV30UN2R | 934068491215 | PMV30UN2 | small signal MOSFET | |
| PMV30UN,215 | 934057773215 | PMV30UN | <=30V N CHANNEL TRENCHFET | SOT23 | TO-236AB | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | PMV30UN2R | 934068491215 | PMV30UN2 | small signal MOSFET | |
| PMN28UN,165 | 934057329165 | PMN28UN | <=30V N CHANNEL TRENCHFET | SOT457 | SC-74 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | PMV30UN2R | 934068491215 | PMV30UN2 | small signal MOSFET | |
| PMV31XN,215 | 934057678215 | PMV31XN | <=30V N CHANNEL TRENCHFET | SOT23 | TO-236AB | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | PMV30UN2R | 934068491215 | PMV30UN2 | small signal MOSFET | |
| PMV37EN,215 | 934065649215 | PMV37EN | small signal MOSFET | SOT23 | TO-236AB | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | PMV37EN2R | 934068492215 | PMV37EN2 | small signal MOSFET | |
| SI2302DS,215 | 934056632215 | SI2302DS | MISCELLANEOUS TRENCHFET | SOT23 | TO-236AB | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | PMV40UN2R | 934068493215 | PMV40UN2 | small signal MOSFET | |
| PMV40UN,215 | 934057952215 | PMV40UN | <=30V N CHANNEL TRENCHFET | SOT23 | TO-236AB | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | PMV40UN2R | 934068493215 | PMV40UN2 | small signal MOSFET | |
| PMN45EN,165 | 934057328165 | PMN45EN | <=30V N CHANNEL TRENCHFET | SOT457 | SC-74 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | PMV45EN2R | 934068494215 | PMV45EN2 | small signal MOSFET | |
| PMV56XN,215 | 934057732215 | PMV56XN | <=30V N CHANNEL TRENCHFET | SOT23 | TO-236AB | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | PMV45EN2R | 934068494215 | PMV45EN2 | small signal MOSFET | |
| PMV45EN,215 | 934057519215 | PMV45EN | <=30V N CHANNEL TRENCHFET | SOT23 | TO-236AB | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | PMV45EN2R | 934068494215 | PMV45EN2 | small signal MOSFET | |
| PMV60EN,215 | 934057520215 | PMV60EN | <=30V N CHANNEL TRENCHFET | SOT23 | TO-236AB | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | PMV45EN2R | 934068494215 | PMV45EN2 | small signal MOSFET | |
| PMR280UN,115 | 934057958115 | PMR280UN | <=30V N CHANNEL TRENCHET | SOT416 | SC-75 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | PMZ290UNYL | 934067834315 | PMZ290UN | small signal MOSFET | |
| PMR400UN,115 | 934057959115 | PMR400UN | <=30V N CHANNEL TRENCHFET | SOT416 | SC-75 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | PMZ390UN,315 | 934060156315 | PMZ390UN | 30V N CHANNEL TRENCHFET (GEN3) | |
| PMR780SN,115 | 934057961115 | PMR780SN | 60V - 75V N CHANNEL TRFT | SOT416 | SC-75 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | PMZ760SN,315 | 934057744315 | PMZ760SN | <=60V N CHANNEL TRENCHFET | |
| PR5331C3HN/C350,55 | 935295151551 | PR5331C3HN/C350 | NFC controller | SOT618-1 | HVQFN40 | Version Withdrawal | Standard End Of Life | Sole | 31-Mar-2015 | 30-Jun-2015 | PR5331C3HN/C370E | 935302531551 | PR5331C3HN/C370 | NFC controller | Replacement part available. Contact your local NXP sales office. |
| PR5331C3HN/C350,51 | 935295151518 | PR5331C3HN/C350 | NFC controller | SOT618-1 | HVQFN40 | Version Withdrawal | Standard End Of Life | Sole | 31-Mar-2015 | 30-Jun-2015 | PR5331C3HN/C370Y | 935302531518 | PR5331C3HN/C370 | NFC controller | Replacement part available. Contact your local NXP sales office. |
| SA56004ATK,118 | 935286444118 | SA56004ATK | SA56004A | SOT782-1 | HVSON8 | Full Withdrawal | Non-Manufacturable | Multiple | 30-Jun-2014 | 30-Jun-2014 | SA56004ADP,118 | 935274562118 | SA56004ADP | REMOTE/LOCAL DIGITAL TEMP SENSOR | Materials not available to build |
| SA56004ETK,118 | 935286445118 | SA56004ETK | SA56004E | SOT782-1 | HVSON8 | Full Withdrawal | Non-Manufacturable | Multiple | 30-Jun-2014 | 30-Jun-2014 | SA56004EDP,118 | 935274567118 | SA56004EDP | REMOTE/LOCAL DIGITAL TEMP SENSOR | Materials not available to build |
| SA601DK,118 | 935164740118 | SA601DK | RF/WIRELESS | SOT266-1 | SSOP20 | Full Withdrawal | Limited | Multiple | 31-Dec-2014 | 30-Jun-2015 | SA601DK,118 | 935164740118 | SA601DK | RF/WIRELESS | Limited wafers |
| SA607DK/01,118 | 935275287118 | SA607DK/01 | RF/WIRELESS | SOT266-1 | SSOP20 | Full Withdrawal | Limited | Multiple | 31-Dec-2014 | 30-Jun-2015 | SA606DK/01,118 | 935275286118 | SA606DK/01 | RF/WIRELESS | Limited wafers |
| SA607DK/01,112 | 935275287112 | SA607DK/01 | RF/WIRELESS | SOT266-1 | SSOP20 | Full Withdrawal | Limited | Multiple | 31-Dec-2014 | 30-Jun-2015 | SA606DK/01,118 | 935275286118 | SA606DK/01 | RF/WIRELESS | Limited wafers |
| SA608DK/01,112 | 935275288112 | SA608DK/01 | RF/WIRELESS | SOT266-1 | SSOP20 | Full Withdrawal | Limited | Multiple | 31-Dec-2014 | 30-Jun-2015 | SA606DK/01,118 | 935275286118 | SA606DK/01 | RF/WIRELESS | Limited wafers |
| SA608DK/01,118 | 935275288118 | SA608DK/01 | RF/WIRELESS | SOT266-1 | SSOP20 | Full Withdrawal | Limited | Multiple | 31-Dec-2014 | 30-Jun-2015 | SA606DK/01,118 | 935275286118 | SA606DK/01 | RF/WIRELESS | Limited wafers |
| HEF4511BT,653 | 933373180653 | HEF4511BT | HEF | SOT109-1 | SO16 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | |
| TDA8566SD/N2S,112 | 935291468112 | TDA8566SD/N2S | CAR RADIO POWER AMPLIFIER | SOT668-2 | RDBS17P | Full Withdrawal | Standard End Of Life | Sole | 31-Mar-2015 | 30-Jun-2015 | | | | | Contact Marketing for Replacement Part |
| BUK9E8R5-40E,127 | 934066415127 | BUK9E8R5-40E | AUTO Trench 6 (SOT226) | SOT226 | I2PAK | Full Withdrawal | Non-Manufacturable | Multiple | 30-Jun-2014 | 30-Jun-2014 | | | | | Not included in product transfer from Global Foundries |
| PCF2113DH/4,557 | 935276328557 | PCF2113DH/4 | DISPLAY DRIVERS | SOT407-1 | LQFP100 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | |
| 74HC652PW,118 | 935248860118 | 74HC652PW | HC/HCT | SOT355-1 | TSSOP24 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | |
| 74HCT7046AN,112 | 933827480112 | 74HCT7046AN | HC/HCT | SOT38-4 | DIP16 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | |
| PESD5V0L6UAS,118 | 934057921118 | PESD5V0L6UAS | Protection diode | SOT505-1 | TSSOP8 | Full Withdrawal | Limited | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | No replacement part |

2014 Mid-Year Product Discontinuation - 201406022DN
 NXP Semiconductor
 June 30, 2014

| | | | | | | | | | | | | | | | | | | | |
|--------------------|--------------|------------------|---------------------------------|-----------|----------|--------------------|----------------------|----------|-------------|-------------|--|--|--|--|--|--|--|--|--|
| 74HC7731D,112 | 935020970112 | 74HC7731D | HC/HCT | SOT109-1 | SO16 | Full Withdrawal | Limited | Multiple | 30-Sep-2014 | 30-Dec-2014 | | | | | | | | | Limited Stock |
| PMPB16XN,115 | 934066866115 | PMPB16XN | small signal MOSFET | SOT1220 | SOT1220 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | | | |
| LH79520N0Q000B1;55 | 935285044557 | LH79520N0Q000B1 | 32-BIT ARM7 | SOT1017-1 | LQFP176 | Full Withdrawal | Limited | Sole | 31-Dec-2014 | 31-Mar-2015 | | | | | | | | | |
| P80C32SBPN,112 | 935255880112 | P80C32SBPN | 51 FAMILY CMOS ROML - 80C32 | SOT129-1 | DIP40 | Full Withdrawal | Limited | Sole | 31-Dec-2014 | 31-Mar-2015 | | | | | | | | | |
| 74HC58DB,112 | 935190150112 | 74HC58DB | HC/HCT | SOT337-1 | SSOP14 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | | | |
| HEF4059BT,653 | 933645510653 | HEF4059BT | HEF | SOT137-1 | SO24 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | | | |
| HEF4511BP,652 | 933324310652 | HEF4511BP | HEF | SOT38-4 | DIP16 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | | | |
| 74HCT7046AD,118 | 933827490118 | 74HCT7046AD | HC/HCT | SOT109-1 | SO16 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | | | |
| 74HC4059N,112 | 933757400112 | 74HC4059N | HC/HCT | SOT101-1 | DIP24 | Full Withdrawal | Limited | Multiple | 30-Sep-2014 | 30-Dec-2014 | | | | | | | | | |
| PSMN010-30MLDX | 934067973115 | PSMN010-30MLD | Trench 9 (SOT1210) | SOT1210 | mLFPK | Full Withdrawal | Limited | Multiple | 30-Sep-2014 | 31-Mar-2015 | | | | | | | | | |
| LD6938CX6/2828PLJ | 934068067118 | LD6938CX6/2828PL | LDO | | NONE | Full Withdrawal | Non-Manufacturabl e | Multiple | 30-Jun-2014 | 30-Jun-2014 | | | | | | | | | |
| TL431AMSDT,215 | 935289169215 | TL431AMSDT | General Purpose Shunt Regulator | SOT23 | TO-236AB | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | | | |
| PCA9522DP,118 | 935292436118 | PCA9522DP | BusBuffer w/hot insertion logic | SOT505-1 | TSSOP8 | Full Withdrawal | Limited | Sole | 31-Dec-2014 | 30-Jun-2015 | | | | | | | | | Limited wafers PCA9522DP |
| BUK654R0-75C,127 | 934064237127 | BUK654R0-75C | 9604 AUTO TRENCH 4 | SOT78A | SIL3P | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | | | Legacy Product EOL |
| PCF8570T/F5,518 | 935154920518 | PCF8570T/F5 | CLIPS | SOT176-1 | SO8 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | | | PCF8570T/F5 |
| 74HC7046AN,112 | 933827460112 | 74HC7046AN | HC/HCT | SOT38-4 | DIP16 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | | | |
| BUK751R6-30E,127 | 934066478127 | BUK751R6-30E | AUTO Trench 6 (SOT78) | SOT78A | SIL3P | Full Withdrawal | Limited | Multiple | 30-Sep-2014 | 31-Mar-2015 | | | | | | | | | Not included in product transfer from Global Foundries |
| 74LV86DB,118 | 935170220118 | 74LV86DB | LV/HC-MOS | SOT337-1 | SSOP14 | Full Withdrawal | Non-Manufacturabl e | Multiple | 30-Jun-2014 | 30-Jun-2014 | | | | | | | | | Inventory depleted |
| PHT8N06LT,135 | 934054610135 | PHT8N06LT | TrenchMOS transistor | SOT223 | SC-73 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | | | Please check with Product line for replacement |
| DH027/01,015 | 935297613015 | DH027/01 | DALSA | | UNCASED | Version Withdrawal | Non-Manufacturabl e | Sole | 30-Jun-2014 | 30-Jun-2014 | | | | | | | | | Dalsa |
| P87C52UBPN,112 | 935253730112 | P87C52UBPN | 51 FAMILY OTP/EPROM - 87C52 | SOT129-1 | DIP40 | Full Withdrawal | Limited | Sole | 31-Dec-2014 | 31-Mar-2015 | | | | | | | | | |
| 74HC652D,112 | 935051190112 | 74HC652D | HC/HCT | SOT137-1 | SO24 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | | | |
| 74HCT4353N,112 | 933757530112 | 74HCT4353N | HC/HCT | SOT146-1 | DIP20 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | | | |
| PHT6N06LT,135 | 934054630135 | PHT6N06LT | TrenchMOS transistor | SOT223 | SC-73 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | | | Please check with Product line for replacement |
| 74LV139D,118 | 935067430118 | 74LV139D | LV/HC-MOS | SOT109-1 | SO16 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | | | |
| DH016V03,015 | 935294446015 | DH016/03 | DALSA | | UNCASED | Version Withdrawal | Non-Manufacturabl e | Sole | 30-Jun-2014 | 30-Jun-2014 | | | | | | | | | Dalsa |
| PMDPB56XN,115 | 934066487115 | PMDPB56XN | small signal MOSFET | SOT1118 | HUSON6 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | | | PMDPB56XNE in development; release Q1 2015 |
| 74HC58D,653 | 933804770653 | 74HC58D | HC/HCT | SOT108-1 | SO14 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | | | |
| PHT6N06T,135 | 934054620135 | PHT6N06T | TrenchMOS transistor | SOT223 | SC-73 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | | | Please check with Product line for replacement |
| BAS316/DLT,115 | 934066102115 | BAS316/DLT | SWITCHING DIODES | SOD323 | SOD2 | Version Withdrawal | Standard End Of Life | Sole | 31-Mar-2015 | 30-Jun-2015 | | | | | | | | | |
| 74HC564D,653 | 933715510653 | 74HC564D | HC/HCT | SOT163-1 | SO20 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | | | |
| P87C51X2BN,112 | 935269606112 | P87C51X2BN | P87C51X2 DIP40 | SOT129-1 | DIP40 | Full Withdrawal | Limited | Sole | 31-Dec-2014 | 31-Mar-2015 | | | | | | | | | |
| 74HC58DB,118 | 935190150118 | 74HC58DB | HC/HCT | SOT337-1 | SSOP14 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | | | |
| BUK962R1-40E,118 | 934066441118 | BUK962R1-40E | AUTO Trench 6 (SOT404) | SOT404 | D2PAK | Full Withdrawal | Limited | Multiple | 30-Sep-2014 | 31-Mar-2015 | | | | | | | | | Not included in product transfer from Global Foundries |
| PH3430AL,115 | 934063086115 | PH3430AL | TRENCH 6 | SOT669 | LFPK | Full Withdrawal | Limited | Multiple | 30-Sep-2014 | 31-Mar-2015 | | | | | | | | | Not included in product transfer from Global Foundries |

2014 Mid-Year Product Discontinuation - 201406022DN
 NXP Semiconductor
 June 30, 2014

| | | | | | | | | | | | | | | | | | |
|--------------------|--------------|-------------------|------------------------------------|----------|----------|--------------------|----------------------|----------|-------------|-------------|--|--|--|--|--|--|--|
| BUK654R8-40C,127 | 934064242127 | BUK654R8-40C | 9604 AUTO TRENCH 4 | SOT78A | SIL3P | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | Legacy Product EOL |
| PH5930AL,115 | 934064952115 | PH5930AL | 5069 TRANS >=1W POWER MOS FET | SOT669 | LPAK | Full Withdrawal | Limited | Multiple | 30-Sep-2014 | 31-Mar-2015 | | | | | | | Not included in product transfer from Global Foundries |
| PJF7993ATW/C1C,512 | 935288603512 | PJF7993ATW/C1C | ABIC | SOT527-1 | | Version Withdrawal | Standard End Of Life | Sole | 31-Mar-2015 | 30-Jun-2015 | | | | | | | Pls. refer to PCN 201312005F01, pls contact Marketing for replacement. |
| BZA820A,115 | 934056046115 | BZA820A | Protection diode | SOT353 | UMT5 | Full Withdrawal | Limited | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | No replacement part |
| 74LV86D,112 | 935081260112 | 74LV86D | LV/HC-MOS | SOT108-1 | SO14 | Full Withdrawal | Non-Manufacturabl e | Multiple | 30-Jun-2014 | 30-Jun-2014 | | | | | | | Inventory depleted |
| BUK652R3-40C,127 | 934064467127 | BUK652R3-40C | 9604 AUTO TRENCH 4 | SOT78A | SIL3P | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | Legacy Product EOL |
| PCF2116CU/10/F1,00 | 935263343005 | PCF2116CU/10/F1 | DISPLAY DRIVERS | | UNCASED | Version Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | |
| PCA9521D,118 | 935292433118 | PCA9521D | Fast dual bidirectional bus buffer | SOT96-1 | SO8 | Full Withdrawal | Limited | Sole | 31-Dec-2014 | 30-Jun-2015 | | | | | | | Limited wafers PCA9521D |
| P80C32X2FN,112 | 935269611112 | P80C32X2FN | P80C32X2 DIP40 | SOT129-1 | DIP40 | Full Withdrawal | Limited | Sole | 31-Dec-2014 | 31-Mar-2015 | | | | | | | |
| 74LV86D,118 | 935081260118 | 74LV86D | LV/HC-MOS | SOT108-1 | SO14 | Full Withdrawal | Non-Manufacturabl e | Multiple | 30-Jun-2014 | 30-Jun-2014 | | | | | | | Inventory depleted |
| DH508/01SL | 935302636015 | DH508/01 | CM33 Polaris2B7x8/01 | | UNCASED | Version Withdrawal | Non-Manufacturabl e | Sole | 30-Jun-2014 | 30-Jun-2014 | | | | | | | Dalsa |
| P87LPC767BN,112 | 935264008112 | P87LPC767BN | P87LPC767 DIP | SOT146-1 | DIP20 | Full Withdrawal | Limited | Sole | 31-Dec-2014 | 31-Mar-2015 | | | | | | | |
| BUK6507-55C,127 | 934064253127 | BUK6507-55C | 9604 AUTO TRENCH 4 | SOT78A | SIL3P | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | Legacy Product EOL |
| PCA9522D,118 | 935292435118 | PCA9522D | BusBuffer w/hot insertion logic | SOT96-1 | SO8 | Full Withdrawal | Limited | Sole | 31-Dec-2014 | 30-Jun-2015 | | | | | | | Limited wafers PCA9522D |
| P87C54X2BN,112 | 935270211112 | P87C54X2BN | P87C54X2B | SOT129-1 | DIP40 | Full Withdrawal | Limited | Sole | 31-Dec-2014 | 31-Mar-2015 | | | | | | | |
| PMN25EN,115 | 934066001115 | PMN25EN | small signal MOSFET | SOT457 | SC-74 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | Please check with Product line for replacement |
| BUK652R6-40C,127 | 934064249127 | BUK652R6-40C | 9604 AUTO TRENCH 4 | SOT78A | SIL3P | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | Legacy Product EOL |
| PMDPB38UNE,115 | 934066526115 | PMDPB38UNE | small signal MOSFET | SOT1118 | HUSON6 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | Please check with Product line for replacement |
| PMT21EN,135 | 934066002135 | PMT21EN | small signal MOSFET | SOT223 | SC-73 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | Please check with Product line for replacement |
| P87LPC762FN,112 | 935266852112 | P87LPC762FN | P87LPC762 | SOT146-1 | DIP20 | Full Withdrawal | Limited | Sole | 31-Dec-2014 | 31-Mar-2015 | | | | | | | |
| PMV30XN,215 | 934065647215 | PMV30XN | small signal MOSFET | SOT23 | TO-236AB | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | PMV30XNE in development; release Q1 2015 |
| TDA19977BHV/15/C1: | 935287375518 | TDA19977BHV/15/C1 | 1.3 HDMI RECEIVER | SOT612-3 | HLQFP144 | Version Withdrawal | Standard End Of Life | Sole | 31-Mar-2015 | 30-Jun-2015 | | | | | | | |
| TL431BSDT,215 | 935290968215 | TL431BSDT | Voltage regulator | SOT23 | TO-236AB | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | |
| BUK7E1R6-30E,127 | 934066509127 | BUK7E1R6-30E | AUTO Trench 6 (sot226) | SOT226 | I2PAK | Full Withdrawal | Limited | Multiple | 30-Sep-2014 | 31-Mar-2015 | | | | | | | Not included in product transfer from Global Foundries |
| P87C51RB2BN,112 | 935271895112 | P87C51RB2BN | 87C51RB2 | SOT129-1 | DIP40 | Full Withdrawal | Limited | Sole | 31-Dec-2014 | 31-Mar-2015 | | | | | | | |
| P87C54SBPN,112 | 935258670112 | P87C54SBPN | C51 FAMILY OTP/EPROM-87C54 | SOT129-1 | DIP40 | Full Withdrawal | Limited | Sole | 31-Dec-2014 | 31-Mar-2015 | | | | | | | |
| BUK961R5-30E,118 | 934066661118 | BUK961R5-30E | AUTO Trench 6 (sot404) | SOT404 | D2PAK | Full Withdrawal | Non-Manufacturabl e | Multiple | 30-Jun-2014 | 30-Jun-2014 | | | | | | | Not included in product transfer from Global Foundries |
| HTMS1101FUG/AM,026 | 935288703026 | HTMS1101FUG/AM | HITAG | | UNCASED | Version Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | Replacement 280pF version. Contact your local NXP sales office. |
| PESD9X7.0L,315 | 934065229315 | PESD9X7.0L | Protection Diode | SOD882 | SOD2 | Full Withdrawal | Limited | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | No replacement part |
| TL431MSDT,215 | 935289171215 | TL431MSDT | General Purpose Shunt Regulator | SOT23 | TO-236AB | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | |
| BUK9E4R4-80E,127 | 934066515127 | BUK9E4R4-80E | AUTO Trench 6 (sot226) | SOT226 | I2PAK | Full Withdrawal | Non-Manufacturabl e | Multiple | 30-Jun-2014 | 30-Jun-2014 | | | | | | | Not included in product transfer from Global Foundries |
| 74HC564N,652 | 933670680652 | 74HC564N | HC/HCT | SOT146-1 | DIP20 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | |
| BUK6510-75C,127 | 934064248127 | BUK6510-75C | 9604 AUTO TRENCH 4 | SOT78A | SIL3P | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | Legacy Product EOL |
| P87C52X2FN,112 | 935269602112 | P87C52X2FN | P87C52X2 PD140 | SOT129-1 | DIP40 | Full Withdrawal | Limited | Sole | 31-Dec-2014 | 31-Mar-2015 | | | | | | | |
| PCA9521DP,118 | 935292434118 | PCA9521DP | Fast dual bidirectional bus buffer | SOT505-1 | TSSOP8 | Full Withdrawal | Limited | Sole | 31-Dec-2014 | 30-Jun-2015 | | | | | | | Limited wafers PCA9521DP |
| 74HC7731N,112 | 935020950112 | 74HC7731N | HC/HCT | SOT38-4 | DIP16 | Full Withdrawal | Limited | Multiple | 30-Sep-2014 | 30-Dec-2014 | | | | | | | Limited Stock |

2014 Mid-Year Product Discontinuation - 201406022DN
 NXP Semiconductor
 June 30, 2014

| | | | | | | | | | | | | | | | | | | |
|--------------------|--------------|---------------------|-------------------------------|----------|----------|--------------------|----------------------|-------------------|-------------|-------------|--|--|--|--|--|--|--|--|
| TDA19977BHV15C1S1 | 935294569551 | TDA19977BHV15/C1/S1 | 1.3 HDMI RECEIVER | SOT612-3 | HLQFP144 | Version Withdrawal | Standard End Of Life | Sole | 31-Mar-2015 | 30-Jun-2015 | | | | | | | | |
| 74HC147N,652 | 933669310652 | 74HC147N | HC/HCT | SOT38-4 | DIP16 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | | |
| P80C51FA-4N,112 | 935260223112 | P80C51FA-4N | 51 FAMILY CMOS ROML - 80C51FA | SOT129-1 | DIP40 | Full Withdrawal | Limited | Sole | 31-Dec-2014 | 31-Mar-2015 | | | | | | | | |
| 74HC243N,652 | 933669070652 | 74HC243N | HC/HCT | SOT27-1 | DIP14 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | | |
| BGA2709,115 | 934056949115 | BGA2709 | MMIC | SOT363 | SC-88 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | | |
| 74HC243D,112 | 933713680112 | 74HC243D | HC/HCT | SOT108-1 | SO14 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | | |
| BUK761R3-30E,118 | 934066499118 | BUK761R3-30E | 960651 | SOT404 | D2PAK | Full Withdrawal | Limited | Multiple | 30-Sep-2014 | 31-Mar-2015 | | | | | | | | Not included in product transfer from Global Foundries |
| 74HC7046ADB,118 | 935190240118 | 74HC7046ADB | HC/HCT | SOT338-1 | SSOP16 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | | |
| 74HC243DB,118 | 935189840118 | 74HC243DB | HC/HCT | SOT337-1 | SSOP14 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | | |
| 74HC563N,652 | 933670670652 | 74HC563N | HC/HCT | SOT146-1 | DIP20 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | | |
| P87C51FB-4N,112 | 935258810112 | P87C51FB-4N | C51 FAMILY OTP/EPROM-87C51FB | SOT129-1 | DIP40 | Full Withdrawal | Limited | Sole | 31-Dec-2014 | 31-Mar-2015 | | | | | | | | |
| P87C52SBPN,112 | 935253690112 | P87C52SBPN | 51 FAMILY OTP/EPROM - 87C52 | SOT129-1 | DIP40 | Full Withdrawal | Limited | Sole | 31-Dec-2014 | 31-Mar-2015 | | | | | | | | |
| 74HCT4353D,112 | 933790940112 | 74HCT4353D | HC/HCT | SOT163-1 | SO20 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | | |
| 74LV86PW,112 | 935181570112 | 74LV86PW | LV/HC-MOS | SOT402-1 | TSSOP14 | Full Withdrawal | Non-Manufacturabl e | Multiple | 30-Jun-2014 | 30-Jun-2014 | | | | | | | | Inventory depleted |
| LH75411N0Q100C0;55 | 935285046557 | LH75411N0Q100C0 | 32-BIT ARM7 | SOT486-1 | LQFP144 | Full Withdrawal | Limited | Sole | 31-Dec-2014 | 31-Mar-2015 | | | | | | | | |
| BUK7E4R0-80E,127 | 934066516127 | BUK7E4R0-80E | AUTO Trench 6 (sot226) | SOT226 | I2PAK | Full Withdrawal | Limited | Multiple | 30-Sep-2014 | 31-Mar-2015 | | | | | | | | Not included in product transfer from Global Foundries |
| 74HCT652D,112 | 935051240112 | 74HCT652D | HC/HCT | SOT137-1 | SO24 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | | |
| TDF8599TH/N2/S480, | 935287818518 | TDF8599TH/N2/S480 | I2C DIAGNOSTICS AMPLIFIER | SOT851-2 | HSOP36 | Version Withdrawal | Standard End Of Life | Customer Specific | 31-Mar-2015 | 30-Jun-2015 | | | | | | | | Contact Marketing for Replacement Part |
| TDA19998HL/C1,557 | 935291362557 | TDA19998HL/C1 | Smart HDMI 1.4 (4 : 1) | SOT407-1 | LQFP100 | Version Withdrawal | Standard End Of Life | Sole | 31-Mar-2015 | 30-Jun-2015 | | | | | | | | |
| PCF8570T/F5,512 | 935154920512 | PCF8570T/F5 | CLIPS | SOT176-1 | SO8 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | | PCF8570T/F5 |
| 74LV139PW,112 | 935174440112 | 74LV139PW | LV/HC-MOS | SOT403-1 | TSSOP16 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | | |
| PMDPB95XNE,115 | 934067055115 | PMDPB95XNE | small signal MOSFET | SOT1118 | HUSON6 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | | PMDPB95XNE2 in development; release Q1 2015 |
| TDA19995HL/C1,557 | 935290123557 | TDA19995HL/C1 | Smart HDMI 1.4 (3 : 1) | SOT407-1 | LQFP100 | Version Withdrawal | Standard End Of Life | Sole | 31-Mar-2015 | 30-Jun-2015 | | | | | | | | |
| P87C51SBPN,112 | 935260176112 | P87C51SBPN | 51 FAMILY OTP/EPROM - 87C51 | SOT129-1 | DIP40 | Full Withdrawal | Limited | Sole | 31-Dec-2014 | 31-Mar-2015 | | | | | | | | |
| TDA19995HL/C1,518 | 935290123518 | TDA19995HL/C1 | Smart HDMI 1.4 (3 : 1) | SOT407-1 | LQFP100 | Version Withdrawal | Standard End Of Life | Sole | 31-Mar-2015 | 30-Jun-2015 | | | | | | | | |
| 74LV374DB,118 | 935080610118 | 74LV374DB | LV/HC-MOS | SOT339-1 | SSOP20 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | | |
| BUK752R3-40C,127 | 934059866127 | BUK752R3-40C | <=40V N CHANNEL TRENCHFET | SOT78A | SIL3P | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | | Legacy Product EOL |
| 74HC4059D,118 | 933757410118 | 74HC4059D | HC/HCT | SOT137-1 | SO24 | Full Withdrawal | Limited | Multiple | 30-Sep-2014 | 30-Dec-2014 | | | | | | | | |
| 74HCT563DB,118 | 935190140118 | 74HCT563DB | HC/HCT | SOT339-1 | SSOP20 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | | |
| TDA3683SD/N2S,112 | 935289142112 | TDA3683SD/N2S | VOLTAGE REGULATOR (8) | SOT889-1 | RDBS23P | Full Withdrawal | Standard End Of Life | Sole | 31-Mar-2015 | 30-Jun-2015 | | | | | | | | Contact Marketing for Replacement Part |
| P89LPC922FN,112 | 935274224112 | P89LPC922FN | 20 PIN LPC900 FAMILY | SOT146-1 | DIP20 | Full Withdrawal | Limited | Sole | 31-Dec-2014 | 31-Mar-2015 | | | | | | | | |
| BUK9E2R3-40E,127 | 934066413127 | BUK9E2R3-40E | AUTO Trench 6 (SOT226) | SOT226 | I2PAK | Full Withdrawal | Limited | Multiple | 30-Sep-2014 | 31-Mar-2015 | | | | | | | | Not included in product transfer from Global Foundries |
| PR5331C3HN/C350;55 | 935295151557 | PR5331C3HN/C350 | NFC controller | SOT618-1 | HVQFN40 | Version Withdrawal | Standard End Of Life | Sole | 31-Mar-2015 | 30-Jun-2015 | | | | | | | | Contact your local NXP sales office for replacement. |
| PH11030AL,115 | 934064955115 | PH11030AL | 5069 TRANS >=1W POWER MOS FET | SOT669 | LFPK | Full Withdrawal | Non-Manufacturabl e | Multiple | 30-Jun-2014 | 30-Jun-2014 | | | | | | | | Not included in product transfer from Global Foundries |
| DH509/01SL | 935302637015 | DH509/01 | CM34 Polaris2B1x8/01 | | UNCASED | Version Withdrawal | Non-Manufacturabl e | Sole | 30-Jun-2014 | 30-Jun-2014 | | | | | | | | Dalsa |

2014 Mid-Year Product Discontinuation - 201406022DN
 NXP Semiconductor
 June 30, 2014

| | | | | | | | | | | | | | | | | | |
|--------------------|--------------|--------------------|-----------------------------|-----------|----------|--------------------|----------------------|----------|-------------|-------------|--|--|--|--|--|--|---|
| BUK951R6-30E,127 | 934066519127 | BUK951R6-30E | AUTO Trench 6 (sot78) | SOT78A | SIL3P | Full Withdrawal | Limited | Multiple | 30-Sep-2014 | 31-Mar-2015 | | | | | | | Not included in product transfer from Global Foundries |
| TDA19977BHV15C1S1' | 935294569557 | TDA19977BHV15C1/S1 | 1.3 HDMI RECEIVER | SOT612-3 | HLQFP144 | Version Withdrawal | Standard End Of Life | Sole | 31-Mar-2015 | 30-Jun-2015 | | | | | | | |
| P87C51RC2FN,112 | 935272151112 | P87C51RC2FN | 87C51RC2 | SOT129-1 | DIP40 | Full Withdrawal | Limited | Sole | 31-Dec-2014 | 31-Mar-2015 | | | | | | | |
| 74HC7731D,118 | 935020970118 | 74HC7731D | HC/HCT | SOT109-1 | SO16 | Full Withdrawal | Limited | Multiple | 30-Sep-2014 | 30-Dec-2014 | | | | | | | Limited Stock |
| 74HC4059D,112 | 933757410112 | 74HC4059D | HC/HCT | SOT137-1 | SO24 | Full Withdrawal | Limited | Multiple | 30-Sep-2014 | 30-Dec-2014 | | | | | | | |
| PSMN010-30YLDX | 934067968115 | PSMN010-30YLD | Trench 9 (SOT669) | SOT669 | LFFPAK | Full Withdrawal | Limited | Multiple | 30-Sep-2014 | 31-Mar-2015 | | | | | | | |
| PMV16UN,215 | 934065646215 | PMV16UN | small signal MOSFET | SOT23 | TO-236AB | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | PMV16XN in development; release Q1 2015 |
| HTMS1301FTK/AF,115 | 935290976115 | HTMS1301FTK/AF | HITAG | SOT899-1 | HVSON2 | Version Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | Contact your local NXP sales office for replacement. |
| 74HC652DB,118 | 935248840118 | 74HC652DB | HC/HCT | SOT340-1 | SSOP24 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | |
| PJF7992ATW/C1C,512 | 935288267512 | PJF7992ATW/C1C | READER CHIPS | SOT527-1 | HTSSOP20 | Version Withdrawal | Standard End Of Life | Sole | 31-Mar-2015 | 30-Jun-2015 | | | | | | | Pls. refer to PCN 201312005F01, pls contact Marketing for replacement. |
| BUK951R9-40E,127 | 934066521127 | BUK951R9-40E | AUTO Trench 6 (sot78) | SOT78A | SIL3P | Full Withdrawal | Limited | Multiple | 30-Sep-2014 | 31-Mar-2015 | | | | | | | Not included in product transfer from Global Foundries |
| 74HC243DB,112 | 935189840112 | 74HC243DB | HC/HCT | SOT337-1 | SSOP14 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | |
| BUK655R0-75C,127 | 934064245127 | BUK655R0-75C | 9604 AUTO TRENCH 4 | SOT78A | SIL3P | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | Legacy Product EOL |
| TDA19998HLC1,551 | 935291362551 | TDA19998HLC1 | Smart HDMI 1.4 (4 : 1) | SOT407-1 | LQFP100 | Version Withdrawal | Standard End Of Life | Sole | 31-Mar-2015 | 30-Jun-2015 | | | | | | | |
| DH039/01SL | 935302121015 | DH039/01 | DALSA | | UNCASED | Version Withdrawal | Non-Manufacturabl e | Sole | 30-Jun-2014 | 30-Jun-2014 | | | | | | | Dalsa |
| 74HCT563DB,112 | 935190140112 | 74HCT563DB | HC/HCT | SOT339-1 | SSOP20 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | |
| PESD5V0L7BAS,118 | 934057922118 | PESD5V0L7BAS | Protection diode | SOT505-1 | TSSOP8 | Full Withdrawal | Limited | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | No replacement part |
| BUK653R4-40C,127 | 934064252127 | BUK653R4-40C | 9604 AUTO TRENCH 4 | SOT78A | SIL3P | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | Legacy Product EOL |
| P87LPC764BN,112 | 935263359112 | P87LPC764BN | P87LPC764BN | SOT146-1 | DIP20 | Full Withdrawal | Limited | Sole | 31-Dec-2014 | 31-Mar-2015 | | | | | | | |
| P80C31SBPN,112 | 935255700112 | P80C31SBPN | 51 FAMILY CMOS ROML - 80C31 | SOT129-1 | DIP40 | Full Withdrawal | Limited | Sole | 31-Dec-2014 | 31-Mar-2015 | | | | | | | |
| DH026/02SL | 935299854015 | DH026/02 | DALSA | | UNCASED | Version Withdrawal | Non-Manufacturabl e | Sole | 30-Jun-2014 | 30-Jun-2014 | | | | | | | Dalsa |
| OM9542/4017V4BA360 | 935283106699 | OM9542/4017V4BA360 | INLAY | | INLAY F | Version Withdrawal | Standard End Of Life | Sole | 31-Mar-2015 | 30-Jun-2015 | | | | | | | Contact NXP sales with any questions. NXP recommends to migrate to newer products, like our P60 and P40 product families. |
| TDA8569Q/N1S,112 | 935289162112 | TDA8569Q/N1S | CARRADIO POWER AMPLIFIERS | SOT411-1 | DBS23P | Version Withdrawal | Standard End Of Life | Sole | 31-Mar-2015 | 30-Jun-2015 | | | | | | | Contact Marketing for Replacement Part |
| 74HC147D,652 | 933714500652 | 74HC147D | HC/HCT | SOT109-1 | SO16 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | |
| 74HCT7273D,112 | 935024080112 | 74HCT7273D | HC/HCT | SOT163-1 | SO20 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | |
| 74HC564D,652 | 933715510652 | 74HC564D | HC/HCT | SOT163-1 | SO20 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | |
| 74LV374D,118 | 935063270118 | 74LV374D | LV/HC-MOS | SOT163-1 | SO20 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | |
| BUK9E6R1-100E,127 | 934066517127 | BUK9E6R1-100E | AUTO Trench 6 (sot226) | SOT226 | I2PAK | Full Withdrawal | Limited | Multiple | 30-Sep-2014 | 31-Mar-2015 | | | | | | | Not included in product transfer from Global Foundries |
| TDA9984BHW/C1,557 | 935292626557 | TDA9984BHW/C1 | HDMI TRANSMITTER | SOT841-4 | HTQFP80 | Version Withdrawal | Standard End Of Life | Sole | 31-Mar-2015 | 30-Jun-2015 | | | | | | | |
| 74LV139N,112 | 935067440112 | 74LV139N | LV/HC-MOS | SOT38-4 | DIP16 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | |
| HEF4059BT,652 | 933645510652 | HEF4059BT | HEF | SOT137-1 | SO24 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | |
| IP4238CZ10,115 | 934065674115 | IP4238CZ10 | ESD protection | SOT1197-1 | HXSON10 | Full Withdrawal | Limited | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | No replacement part. |
| PMN22XN,115 | 934066304115 | PMN22XN | small signal MOSFET | SOT457 | SC-74 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | Please check with Product line for replacement |
| 74HC7046ADB,112 | 935190240112 | 74HC7046ADB | HC/HCT | SOT338-1 | SSOP16 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | |
| 74HC563D,653 | 933713840653 | 74HC563D | HC/HCT | SOT163-1 | SO20 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | |

2014 Mid-Year Product Discontinuation - 201406022DN
 NXP Semiconductor
 June 30, 2014

| | | | | | | | | | | | | | | | |
|--------------------|--------------|-----------------|------------------------|-----------|----------|--------------------|----------------------|----------|-------------|-------------|--|--|--|--|--|
| 74LV139D,112 | 935067430112 | 74LV139D | LV/HC-MOS | SOT109-1 | SO16 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | |
| BUK654R6-55C,127 | 934064246127 | BUK654R6-55C | 9604 AUTO TRENCH 4 | SOT78A | SIL3P | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | Legacy Product EOL |
| 74HCT4059D,118 | 933757430118 | 74HCT4059D | HC/HCT | SOT137-1 | SO24 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | |
| PMV65UN,215 | 934066505215 | PMV65UN | small signal MOSFET | SOT23 | TO-236AB | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | PMV65UNE in development; release Q1 2015 |
| HTMS8301FTK/AF,115 | 935290977115 | HTMS8301FTK/AF | HITAG | SOT899-1 | HVSON2 | Version Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | Contact your local NXP sales office for replacement. |
| TDA19995HL/C1,551 | 935290123551 | TDA19995HL/C1 | Smart HDMI 1.4 (3 : 1) | SOT407-1 | LQFP100 | Version Withdrawal | Standard End Of Life | Sole | 31-Mar-2015 | 30-Jun-2015 | | | | | |
| PH9030AL,115 | 934063092115 | PH9030AL | TRENCH 6 | SOT669 | LFPK | Full Withdrawal | Limited | Multiple | 30-Sep-2014 | 31-Mar-2015 | | | | | Not included in product transfer from Global Foundries |
| P87C51RC2BN,112 | 935272150112 | P87C51RC2BN | 87C51RC2 | SOT129-1 | DIP40 | Full Withdrawal | Limited | Sole | 31-Dec-2014 | 31-Mar-2015 | | | | | |
| TDA19997HL/C1,557 | 935290034557 | TDA19997HL/C1 | Smart HDMI 1.4 (4 : 1) | SOT407-1 | LQFP100 | Version Withdrawal | Standard End Of Life | Sole | 31-Mar-2015 | 30-Jun-2015 | | | | | |
| TDA9984BHW/C1,518 | 935292626518 | TDA9984BHW/C1 | HDMI TRANSMITTER | SOT841-4 | HTQFP80 | Version Withdrawal | Standard End Of Life | Sole | 31-Mar-2015 | 30-Jun-2015 | | | | | |
| TDA19997HL/C1,518 | 935290034518 | TDA19997HL/C1 | Smart HDMI 1.4 (4 : 1) | SOT407-1 | LQFP100 | Version Withdrawal | Standard End Of Life | Sole | 31-Mar-2015 | 30-Jun-2015 | | | | | |
| 74HC147DB,118 | 935189670118 | 74HC147DB | HC/HCT | SOT338-1 | SSOP16 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | |
| BUK9E15-60E,127 | 934066659127 | BUK9E15-60E | AUTO Trench 6 (sot226) | SOT226 | I2PAK | Full Withdrawal | Limited | Multiple | 30-Sep-2014 | 31-Mar-2015 | | | | | Not included in product transfer from Global Foundries |
| 74HCT652D,118 | 935051240118 | 74HCT652D | HC/HCT | SOT137-1 | SO24 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | |
| 74HC4059DB,112 | 935190010112 | 74HC4059DB | HC/HCT | SOT340-1 | SSOP24 | Full Withdrawal | Limited | Multiple | 30-Sep-2014 | 30-Dec-2014 | | | | | Limited Stock |
| TL431BMSDT,215 | 935290969215 | TL431BMSDT | Voltage regulator | SOT23 | TO-236AB | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | |
| PMV20XN,215 | 934065648215 | PMV20XN | small signal MOSFET | SOT23 | TO-236AB | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | PMV16XN in development; release Q1 2015 |
| LH75401N0Q100C0,55 | 935285049551 | LH75401N0Q100C0 | 32-BIT ARM7 | SOT486-1 | LQFP144 | Full Withdrawal | Limited | Sole | 31-Dec-2014 | 31-Mar-2015 | | | | | |
| 74HC652D,118 | 935051190118 | 74HC652D | HC/HCT | SOT137-1 | SO24 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | |
| 74LV86DB,112 | 935170220112 | 74LV86DB | LV/HC-MOS | SOT337-1 | SSOP14 | Full Withdrawal | Non-Manufacturabl e | Multiple | 30-Jun-2014 | 30-Jun-2014 | | | | | Inventory depleted |
| BUK9E3R7-60E,127 | 934066631127 | BUK9E3R7-60E | AUTO Trench 6 (sot226) | SOT226 | I2PAK | Full Withdrawal | Non-Manufacturabl e | Multiple | 30-Jun-2014 | 30-Jun-2014 | | | | | Not included in product transfer from Global Foundries |
| BUK653R2-55C,127 | 934064468127 | BUK653R2-55C | 9604 AUTO TRENCH 4 | SOT78A | SIL3P | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | Legacy Product EOL |
| HEF4511BT,652 | 933373180652 | HEF4511BT | HEF | SOT109-1 | SO16 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | |
| 74HCT7273N,112 | 935024070112 | 74HCT7273N | HC/HCT | SOT146-1 | DIP20 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | |
| BUK761R5-40EJ | 934067767118 | BUK761R5-40E | Auto Trench 6 (SOT404) | SOT404A | D2PAK | Full Withdrawal | Limited | Multiple | 30-Sep-2014 | 31-Mar-2015 | | | | | Not included in product transfer from Global Foundries |
| BUK9E2R8-60E,127 | 934066513127 | BUK9E2R8-60E | AUTO Trench 6 (sot226) | SOT226 | I2PAK | Full Withdrawal | Limited | Multiple | 30-Sep-2014 | 31-Mar-2015 | | | | | Not included in product transfer from Global Foundries |
| TDA8034BT/C1,112 | 935295481112 | TDA8034BT/C1 | CT READER ICS ANALOG | SOT109-1 | SO16 | Version Withdrawal | Standard End Of Life | Sole | 31-Mar-2015 | 30-Jun-2015 | | | | | Replacement part TDA8035 available. Contact your local NXP sales office. |
| PMN35EN,115 | 934065376115 | PMN35EN | small signal MOSFET | SOT457 | SC-74 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | Please check with Product line for replacement |
| BUK652R1-30C,127 | 934064241127 | BUK652R1-30C | 9604 AUTO TRENCH 4 | SOT78A | SIL3P | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | Legacy Product EOL |
| 74LV139DB,118 | 935165980118 | 74LV139DB | LV/HC-MOS | SOT338-1 | SSOP16 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | |
| LH79525N0Q100A1,55 | 935285052557 | LH79525N0Q100A1 | 32-BIT ARM7 | SOT1017-1 | LQFP176 | Full Withdrawal | Limited | Sole | 31-Dec-2014 | 31-Mar-2015 | | | | | |
| 74HCT563N,652 | 933670920652 | 74HCT563N | HC/HCT | SOT146-1 | DIP20 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | |
| HTMS1301FTB/AF,115 | 935290068115 | HTMS1301FTB/AF | HITAG | SOT1122 | XSON3 | Version Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | Contact your local NXP sales office for replacement. |
| PMF250XN,115 | 934066323115 | PMF250XN | small signal MOSFET | SOT323 | SC-70 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | PMF250XNE in development; release Q2 2015 |
| PESD5V0L6US,118 | 934057934118 | PESD5V0L6US | Protection diode | SOT96-1 | SO8 | Full Withdrawal | Limited | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | No replacement part |
| 74LV139BQ,115 | 935285576115 | 74LV139BQ | 74LV139BQ | SOT763-1 | DHVQFN16 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | |

2014 Mid-Year Product Discontinuation - 201406022DN
 NXP Semiconductor
 June 30, 2014

| | | | | | | | | | | | | | | | | | | |
|--------------------|--------------|--------------------|------------------------------------|----------|----------|--------------------|----------------------|----------|-------------|-------------|--|--|--|--|--|--|--|---|
| 74HC563D,652 | 933713840652 | 74HC563D | HC/HCT | SOT163-1 | SO20 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | | |
| NVT2004TL,115 | 935292071115 | NVT2004TL | Bidirectional voltage level xlator | SOT973-2 | HXSON12U | Full Withdrawal | Non-Manufacturabl e | Sole | 30-Jun-2014 | 30-Jun-2014 | | | | | | | | NVT2004TL Materials not available to build |
| TL431ASDT,215 | 935288351215 | TL431ASDT | General Purpose Shunt Regulator | SOT23 | TO-236AB | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | | |
| 74HC652PW,112 | 935248860112 | 74HC652PW | HC/HCT | SOT355-1 | TSSOP24 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | | |
| P5CD080AA/T0B11140 | 935285668699 | P5CD080AA/T0B11140 | 08BIT DIF | | INLAY A | Version Withdrawal | Standard End Of Life | Sole | 31-Mar-2015 | 30-Jun-2015 | | | | | | | | Contact NXP sales with any questions. NXP recommends to migrate to newer products, like our P60 and P40 product families. |
| BGA2712,115 | 934056948115 | BGA2712 | MMIC | SOT363 | SC-88 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | | |
| 74HC147DB,112 | 935189670112 | 74HC147DB | HC/HCT | SOT338-1 | SSOP16 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | | |
| 74HC4059DB,118 | 935190010118 | 74HC4059DB | HC/HCT | SOT340-1 | SSOP24 | Full Withdrawal | Limited | Multiple | 30-Sep-2014 | 30-Dec-2014 | | | | | | | | Limited Stock |
| 74HCT7273D,118 | 935024080118 | 74HCT7273D | HC/HCT | SOT163-1 | SO20 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | | |
| HTCICC6401EW/C7,02 | 935294192026 | HTCICC6401EW/C7 | HITAG | | UNCASED | Version Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | | Contact your local NXP sales office for replacement. |
| 74LV139PW,118 | 935174440118 | 74LV139PW | LV/HC-MOS | SOT403-1 | TSSOP16 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | | |
| P5CD128AL/T0A05079 | 935293357699 | P5CD128AL/T0A05079 | 08BIT DIF | | INLAY | Version Withdrawal | Standard End Of Life | Sole | 31-Mar-2015 | 30-Jun-2015 | | | | | | | | Contact NXP sales with any questions. NXP recommends to migrate to newer products, like our P60 and P40 product families. |
| PMN20EN,115 | 934065662115 | PMN20EN | small signal MOSFET | SOT457 | SC-74 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | | Please check with Product line for replacement |
| 74LV86PW,118 | 935181570118 | 74LV86PW | LV/HC-MOS | SOT402-1 | TSSOP14 | Full Withdrawal | Non-Manufacturabl e | Multiple | 30-Jun-2014 | 30-Jun-2014 | | | | | | | | Inventory depleted |
| HTMS8301FUG/AM,005 | 935288713005 | HTMS8301FUG/AM | HITAG | | UNCASED | Version Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | | Contact your local NXP sales office for replacement. |
| P87C58X2BN,112 | 935270378112 | P87C58X2BN | P87C58X2 PDIP | SOT129-1 | DIP40 | Full Withdrawal | Limited | Sole | 31-Dec-2014 | 31-Mar-2015 | | | | | | | | |
| PMN25UN,115 | 934065916115 | PMN25UN | small signal MOSFET | SOT457 | SC-74 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | | Please check with Product line for replacement |
| 74LV86N,112 | 935081270112 | 74LV86N | LV/HC-MOS | SOT27-1 | DIP14 | Full Withdrawal | Non-Manufacturabl e | Multiple | 30-Jun-2014 | 30-Jun-2014 | | | | | | | | Inventory depleted |
| 74HCT563D,652 | 933713850652 | 74HCT563D | HC/HCT | SOT163-1 | SO20 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | | |
| BUK968R3-40E,118 | 934066446118 | BUK968R3-40E | AUTO Trench 6 (SOT404) | SOT404 | D2PAK | Full Withdrawal | Limited | Multiple | 30-Sep-2014 | 31-Mar-2015 | | | | | | | | Not included in product transfer from Global Foundries |
| BUK754R3-75C,127 | 934060122127 | BUK754R3-75C | 60-75V N CH TRENCHFET | SOT78A | SIL3P | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | | Legacy Product EOL |
| BUK653R5-55C,127 | 934064238127 | BUK653R5-55C | 9604 AUTO TRENCH 4 | SOT78A | SIL3P | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | | Legacy Product EOL |
| TDA19977BHV/15/C1, | 935287375551 | TDA19977BHV/15/C1 | 1.3 HDMI RECEIVER | SOT612-3 | HLQFP144 | Version Withdrawal | Standard End Of Life | Sole | 31-Mar-2015 | 30-Jun-2015 | | | | | | | | |
| PHT4NQ10LT,135 | 934056122135 | PHT4NQ10LT | 100V N CHANNEL TRENCHFET | SOT223 | SC-73 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | | Please check with Product line for replacement |
| 74HC7046AD,118 | 933827470118 | 74HC7046AD | HC/HCT | SOT109-1 | SO16 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | | |
| 74HCT563D,653 | 933713850653 | 74HCT563D | HC/HCT | SOT163-1 | SO20 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | | |
| 74HCT7046AD,112 | 933827490112 | 74HCT7046AD | HC/HCT | SOT109-1 | SO16 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | | |
| PSMN8R5-108ESQ | 934068134127 | PSMN8R5-108ES | Trench 6 (SOT226) | SOT226 | I2PAK | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | | |
| PESD5V0L7BS,118 | 934057935118 | PESD5V0L7BS | Protection diode | SOT96-1 | SO8 | Full Withdrawal | Limited | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | | No replacement part |
| BUK754R0-40C,127 | 934063295127 | BUK754R0-40C | 9604 AUTO TRENCH 4 | SOT78A | SIL3P | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | | | Legacy Product EOL |
| BUK9E1R9-40E,127 | 934066511127 | BUK9E1R9-40E | AUTO Trench 6 (sot226) | SOT226 | I2PAK | Full Withdrawal | Limited | Multiple | 30-Sep-2014 | 31-Mar-2015 | | | | | | | | Not included in product transfer from Global Foundries |
| BUK961R4-30E,118 | 934066491118 | BUK961R4-30E | AUTO Trench 6 (SOT404) | SOT404 | D2PAK | Full Withdrawal | Limited | Multiple | 30-Sep-2014 | 31-Mar-2015 | | | | | | | | Not included in product transfer from Global Foundries |
| TDA8034BT/C1,118 | 935295481118 | TDA8034BT/C1 | CT READER ICS ANALOG | SOT109-1 | SO16 | Version Withdrawal | Standard End Of Life | Sole | 31-Mar-2015 | 30-Jun-2015 | | | | | | | | Replacement part TDA8035 available. Contact your local NXP sales office. |

2014 Mid-Year Product Discontinuation - 201406022DN
 NXP Semiconductor
 June 30, 2014

| | | | | | | | | | | | | | | | | |
|--------------------|--------------|---------------------|---------------------------------|----------|----------|--------------------|----------------------|----------|-------------|-------------|--|--|--|--|--|--|
| LPC1114FN28/102,12 | 935297016129 | LPC1114FN28/102 | 32-bit ARM M0 Core | SOT117-1 | DIP28 | Full Withdrawal | Limited | Sole | 31-Dec-2014 | 31-Mar-2015 | | | | | | |
| 74HC652N,112 | 935051260112 | 74HC652N | HC/HCT | SOT101-1 | DIP24 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | |
| DH014/06,015 | 935294454015 | DH014/06 | DALSA | | UNCASED | Version Withdrawal | Non-Manufacturabl e | Sole | 30-Jun-2014 | 30-Jun-2014 | | | | | | Dalsa |
| BGA2022,115 | 934056238115 | BGA2022 | MMIC MIXER | SOT363 | SC-88 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | |
| 74LV139DB,112 | 935165980112 | 74LV139DB | LV/HC-MOS | SOT338-1 | SSOP16 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | |
| PUML1,115 | 934062098115 | PUML1 | COMPLEX DISCRETE | SOT363 | SC-88 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | |
| 74LV374PW,118 | 935174870118 | 74LV374PW | LV/HC-MOS | SOT360-1 | TSSOP20 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | |
| BUK653R7-30C,127 | 934064244127 | BUK653R7-30C | 9604 AUTO TRENCH 4 | SOT78A | SIL3P | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | Legacy Product EOL |
| 74LV374DB,112 | 935080610112 | 74LV374DB | LV/HC-MOS | SOT339-1 | SSOP20 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | |
| HEF4059BP,652 | 933507930652 | HEF4059BP | HEF | SOT101-1 | DIP24 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | |
| 74HC7046AD,112 | 933827470112 | 74HC7046AD | HC/HCT | SOT109-1 | SO16 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | |
| 74HC58N,652 | 933804760652 | 74HC58N | HC/HCT | SOT27-1 | DIP14 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | |
| BZA100,118 | 934034860118 | BZA100 | Protection diode | SOT163-1 | SO20 | Full Withdrawal | Limited | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | No replacement part |
| P87LPC767FN,112 | 935267192112 | P87LPC767FN | P87LPC767 DIP | SOT146-1 | DIP20 | Full Withdrawal | Limited | Sole | 31-Dec-2014 | 31-Mar-2015 | | | | | | |
| P87C51FA-4N,112 | 935253960112 | P87C51FA-4N | 51 FAMILY OTP/EPROM - 87C51FA | SOT129-1 | DIP40 | Full Withdrawal | Limited | Sole | 31-Dec-2014 | 31-Mar-2015 | | | | | | |
| 74HC4353D,652 | 933790930652 | 74HC4353D | HC/HCT | SOT163-1 | SO20 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | |
| PMF63UN,115 | 934066616115 | PMF63UN | small signal MOSFET | SOT323 | SC-70 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | PMF63UNE in development; release Q1 2015 |
| P87LPC768FN,112 | 935267488112 | P87LPC768FN | 87LPC768 DIP20 | SOT146-1 | DIP20 | Full Withdrawal | Limited | Sole | 31-Dec-2014 | 31-Mar-2015 | | | | | | |
| TDA19977BHV15C1S1: | 935294569518 | TDA19977BHV15/C1/S1 | 1.3 HDMI RECEIVER | SOT612-3 | HLQFP144 | Version Withdrawal | Standard End Of Life | Sole | 31-Mar-2015 | 30-Jun-2015 | | | | | | |
| 74HC243D,118 | 933713680118 | 74HC243D | HC/HCT | SOT108-1 | SO14 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | |
| BUK9E1R6-30E,127 | 934066508127 | BUK9E1R6-30E | AUTO Trench 6 (sot226) | SOT226 | I2PAK | Full Withdrawal | Limited | Multiple | 30-Sep-2014 | 31-Mar-2015 | | | | | | Not included in product transfer from Global Foundries |
| 74HC147D,653 | 933714500653 | 74HC147D | HC/HCT | SOT109-1 | SO16 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | |
| 74HCT652N,112 | 935051180112 | 74HCT652N | HC/HCT | SOT101-1 | DIP24 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | |
| TL431SDT,215 | 935288353215 | TL431SDT | General Purpose Shunt Regulator | SOT23 | TO-236AB | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | |
| 74HCT4059N,112 | 933757420112 | 74HCT4059N | HC/HCT | SOT101-1 | DIP24 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | |
| TDA8002CG/C1,518 | 935261709518 | TDA8002CG/C1 | CT READER ICS ANALOG | SOT401-1 | LQFP32 | Version Withdrawal | Standard End Of Life | Sole | 31-Mar-2015 | 30-Jun-2015 | | | | | | Replacement part TDA8035 available. Contact your local NXP sales office. |
| BUK761R4-30E,118 | 934066662118 | BUK761R4-30E | AUTO Trench 6 (SOT404) | SOT404 | D2PAK | Full Withdrawal | Limited | Multiple | 30-Sep-2014 | 31-Mar-2015 | | | | | | Not included in product transfer from Global Foundries |
| 74HCT4353D,118 | 933790940118 | 74HCT4353D | HC/HCT | SOT163-1 | SO20 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | |
| 74LV374D,112 | 935063270112 | 74LV374D | LV/HC-MOS | SOT163-1 | SO20 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | |
| PH1525AL,115 | 934064726115 | PH1525AL | 9656 Trench 6 | SOT669 | LFPK | Full Withdrawal | Non-Manufacturabl e | Multiple | 30-Jun-2014 | 30-Jun-2014 | | | | | | Not included in product transfer from Global Foundries |
| 74HC58D,652 | 933804770652 | 74HC58D | HC/HCT | SOT108-1 | SO14 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | |
| 74LV374PW,112 | 935174870112 | 74LV374PW | LV/HC-MOS | SOT360-1 | TSSOP20 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | |
| BUK652R0-30C,127 | 934064466127 | BUK652R0-30C | 9604 AUTO TRENCH 4 | SOT78A | SIL3P | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | Legacy Product EOL |
| 74HC4353N,652 | 933757520652 | 74HC4353N | HC/HCT | SOT146-1 | DIP20 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | |
| 74HC4353D,653 | 933790930653 | 74HC4353D | HC/HCT | SOT163-1 | SO20 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | |

2014 Mid-Year Product Discontinuation - 201406022DN
 NXP Semiconductor
 June 30, 2014

| | | | | | | | | | | | | | | | | |
|--------------------|--------------|-------------------|------------------------|----------|----------|--------------------|----------------------|----------|-------------|-------------|--|--|--|--|--|--|
| TDA19998HL/C1,518 | 935291362518 | TDA19998HL/C1 | Smart HDMI 1.4 (4 : 1) | SOT407-1 | LQFP100 | Version Withdrawal | Standard End Of Life | Sole | 31-Mar-2015 | 30-Jun-2015 | | | | | | |
| 74LV86BQ,115 | 935285561115 | 74LV86BQ | 74LV86BQ | SOT762-1 | DHVQFN14 | Full Withdrawal | Non-Manufacturabl e | Multiple | 30-Jun-2014 | 30-Jun-2014 | | | | | | Inventory depleted |
| P87LPC764FN,112 | 935266845112 | P87LPC764FN | P87LPC764 | SOT146-1 | DIP20 | Full Withdrawal | Limited | Sole | 31-Dec-2014 | 31-Mar-2015 | | | | | | |
| HTMS1301FUG/AM,005 | 935288705005 | HTMS1301FUG/AM | HITAG | | UNCASED | Version Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | Contact your local NXP sales office for replacement. |
| BUK9E3R2-40E,127 | 934066414127 | BUK9E3R2-40E | AUTO Trench 6 (SOT226) | SOT226 | I2PAK | Full Withdrawal | Limited | Multiple | 30-Sep-2014 | 31-Mar-2015 | | | | | | Not included in product transfer from Global Foundries |
| 74LV374N,112 | 935063260112 | 74LV374N | LV/HC-MOS | SOT146-1 | DIP20 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | |
| 74HCT4059D,112 | 933757430112 | 74HCT4059D | HC/HCT | SOT137-1 | SO24 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | |
| TDA19977BHV/15/C1' | 935287375557 | TDA19977BHV/15/C1 | 1.3 HDMI RECEIVER | SOT612-3 | HLQFP144 | Version Withdrawal | Standard End Of Life | Sole | 31-Mar-2015 | 30-Jun-2015 | | | | | | |
| 74HC652DB,112 | 935248840112 | 74HC652DB | HC/HCT | SOT340-1 | SSOP24 | Full Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | |
| TDA9984BHW/C1,551 | 935292626551 | TDA9984BHW/C1 | HDMI TRANSMITTER | SOT841-4 | HTQFP80 | Version Withdrawal | Standard End Of Life | Sole | 31-Mar-2015 | 30-Jun-2015 | | | | | | |
| P87C52X2BN,112 | 935269601112 | P87C52X2BN | P87C52X2 PDI40 | SOT129-1 | DIP40 | Full Withdrawal | Limited | Sole | 31-Dec-2014 | 31-Mar-2015 | | | | | | |
| BGM1012,115 | 934056906115 | BGM1012 | MMIC | SOT363 | SC-88 | Full Withdrawal | Non-Manufacturabl e | Multiple | 30-Jun-2014 | 30-Jun-2014 | | | | | | |
| P87LPC762BN,112 | 935264004112 | P87LPC762BN | P87LPC762 DIP | SOT146-1 | DIP20 | Full Withdrawal | Limited | Sole | 31-Dec-2014 | 31-Mar-2015 | | | | | | |
| HTMS8301FTB/AF,115 | 935290074115 | HTMS8301FTB/AF | HITAG | SOT1122 | XSON3 | Version Withdrawal | Standard End Of Life | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | Contact your local NXP sales office for replacement. |
| BZA418A,165 | 934057138165 | BZA418A | Protection diode | SOT457 | SC-74 | Full Withdrawal | Limited | Multiple | 31-Dec-2014 | 30-Jun-2015 | | | | | | No replacement part |
| TDA19997HL/C1,551 | 935290034551 | TDA19997HL/C1 | Smart HDMI 1.4 (4 : 1) | SOT407-1 | LQFP100 | Version Withdrawal | Standard End Of Life | Sole | 31-Mar-2015 | 30-Jun-2015 | | | | | | |