

Philips Semiconductors

February 13, 2006

Attention: Philips' Customer's Materials Managers, Customer's Purchasing Managers and Philips' Products Managers

Subject: Philips Semiconductors' Product Discontinuation Notice Number DN-56, Correction Notice

Dear Philips Semiconductors' Customer or Distributor:

This letter outlines certain corrects and changes to information contained in Philips December 31, 2005 Product Discontinuation Notice Number DN-56 as follows:

1. Reference Exhibit A to DN-56 ("SOD87 Rectifier and Zener TVS Discontinued Part Types"):

A. On January 26, 2006, Philips' Bipolar Product Line, Business Line Power Management issued a Discontinued Product Correction Notice Entitled "Change of Availability Status of SOD87 Products". A copy of this notice letter is attached to and made part of this DN-56 Correction Notice for your review.

The attached January 26th Philips' Business Line Notice letter amends the specific SOD87 Part Types that were incorrectly stated in Philips' December 31, 2006 DN-56 Exhibit A as having a Code 3 ("Unlimited Supply Availability"). The ordering supply availability for these SOD87 Part Types is hereby corrected to indicate that these Part Types actually have a Code 2 ("Limited Availability").

This Limited Availability condition is due to Philips' restricted production and technical capability for continued manufacturing of these specific SOD87 Products. Therefore, Philips' customers and distributors for these SOD87 products need to place their final last time buy orders "As Soon As Possible" (now by March 31, 2006) to insure the highest degree of confidence that Philips can meet your last time supply requirements.

Refer to the attached Philips January 26, 2006 letter for the affected SOD87 Part Types and more information. Additionally we recommend that you consult Philips' Business Line, Bipolar Product Marketing Management for more specific details and current SOD87 product availability status.

B. SOD87 Product Replacement Correction:

In addition to the revised Product Availability change for the SOD87 Products, there is an additional correction for the below listed SOD87 Part Types regarding "Product Replacement" information. The below listed SOD87 Part Types originally had "Product Replacement Information" stated on both DN-56, as well as on Philips Business Line January 26, 2006 Notice Letter referenced above. Philips hereby corrects this information to now correctly show that there are NO KNOWN REPLACEMENT PRODUCTS for the below listed SOD87 Part Types.



Philips Semiconductors

Column 1 Type Number	Column 3 Description	Column 4 12NC	Column 10 Replacement Part
PRS07D	PRODUCT PRS07D (SOD87)	934058233115	None
PRS07D	PRODUCT PRS07D (SOD87)	934058233135	None
PRS07G	PRODUCT PRS07G (SOD87)	934058234115	None
PRS07G	PRODUCT PRS07G (SOD87)	934058234135	None
PRS07J	PRODUCT PRS07J (SOD87)	934058235115	None
PRS07J	PRODUCT PRS07J (SOD87)	934058235135	None
PS07D	PRODUCT PS07D (SOD87)	934058236115	None
PS07D	PRODUCT PS07D (SOD87)	934058236135	None
PS07G	PRODUCT PS07G (SOD87)	934058237115	None
PS07G	PRODUCT PS07G (SOD87)	934058237135	None
PS07J	PRODUCT PS07J (SOD87)	934058238115	None
PS07J	PRODUCT PS07J (SOD87)	934058238135	None

2. Reference DN-56 Exhibit B (“Reactivated Previously Discontinued Philips Products”):

This confirms to your company that Philips is now replacing the original DN-56 Exhibit B (“Reactivated Previously Discontinued Philips Products”) listing with the following Corrected Exhibit B Re-activated Products List.

This Exhibit B correction is required due to a system problem in recently changed methodology as to how re-activated previously discontinued products are captured in Philips systems. Therefore, the below listed products now represents Philips’ correct “DN-56 Re-activated Previously Discontinued Products re-activated from Start Date: 2005-06-01 to End Date: 2005-11-30.

Please destroy the original DN-56 Exhibit B and replace it with the below correct list of Philips DN-56 Re-activated Part Types:

12NC	PREV DN	Description	Previous State	Date Of Demotion	6TG	MAG	Current State
934055159127	DN48	BUJ103AX	WIT	09/02/05	9633Z9	R72	RFS
935227460518	DN48	SAA7702H/N215/S420	WIT	07/15/05	510500	R32	RFS
934055700118	DN50	PHD18NQ10T	DOD	06/22/05	9654SV	R73	RFS
933366480215	DN50	BSR12	WIT	09/02/05	45177B	R77	RFS
935263725112	DN54	TDA3674AT/N1	DOD	06/29/05	403475	R79	RFS
935273878529	DN54	P89LPC932FDH	WIT	10/03/05	560224	R05	RFS
935263725118	DN54	TDA3674AT/N1	DOD	06/29/05	403475	R79	RFS
935271552557	DN55	UDA1355H/N2	DOD	08/26/05	510234	R30	CQS
935271552518	DN55	UDA1355H/N2	DOD	08/26/05	510234	R30	CQS
934058859135	DN55	BAS221/A	DOD	08/05/05	4558A1	R76	RFS
934058859115	DN55	BAS221/A	DOD	08/05/05	4558A1	R76	RFS
935271552551	DN55	UDA1355H/N2	DOD	08/26/05	510234	R30	CQS



Philips Semiconductors

Sincerely,

PHILIPS SEMICONDUCTORS

Craig Ash
Contracts Legal Department Product Discontinuation Notice Management

Attachment: Philips Notice Letter Dated January 26, 2006 Titled Change of Availability Status of SOD87 Products”.

