

NXP Semiconductors
Product Discontinuation DN64
Exhibit B - Product Reactivation List and Clarification Notice on Previously
Discontinued Products

June 30, 2009

A. Reactivation List

Description	12NC	Product Status	Discontinued on DN#
74LVC109D	935191050112	RFS	DN37
74LVC109D	935191050118	RFS	DN37
74LVC109DB	935191060112	RFS	DN37
74LVC109DB	935191060118	RFS	DN37
74LVC109PW	935191070112	RFS	DN37
74LVC109PW	935191070118	RFS	DN37
74LVTH244AD	935262069112	RFS	DN41
74LVTH244AD	935262069118	RFS	DN41
74LVTH244ADB	935262070112	RFS	DN41
74LVTH244ADB	935262070118	RFS	DN41
74LVTH244APW	935262071112	RFS	DN41
74LVTH244APW	935262071118	RFS	DN41
BLF246B	934001090112	RFS	DN38
BUK217-50Y	934056318118	RFS	DN62
BUK217-50Y	934056318118	RFS	DN62
P5CD036EV0/T0M92361	935283295118	RFS	DN62
P5CC036EW1/T1D5220	935282349005	RFS	DN62
P5CD036EV0/T0M65014	935278753118	RFS	DN62
P5CD072EV1/T0PBSG64	935281993118	RFS	DN62
P5CD072EW1/T0PE8780	935283413005	RFS	DN62
PCA2002TK/1	935275138118	RFS	DN62
PCF2100CT/F1	935195690112	RFS	DN41
PCF2100CT/F1	935195690112	RFS	DN41
PCF2100CT/F1	935195690118	RFS	DN41
PCF2100CT/F1	935195690118	RFS	DN41
PCF2113AU/10/F4	935264031005	RFS	DN45
PCF2113AU/10/F4	935264031005	RFS	DN45
PCF8533U/2E/F2	935264030026	RFS	DN59
PCF8533U/2E/F2	935264030026	RFS	DN59
PCF8577CU/F3	935263161026	RFS	DN41
PCF8577CU/F3	935263161026	RFS	DN41
PHB110NQ08T	934058275118	RFS	DN62
PIP401	934057294118	RFS	DN62
PNX1503E/G	935278338557	RFS	DN62
SC16C2550IB48	935270020151	RFS	DN59
SC16C554IB80	935270075528	RFS	DN59
SC16C752IB48	935270055128	RFS	DN59
TDA6107AJF/N1	935263644112	RFS	DN45
TDA8706AM/C3	935260792112	RFS	DN49
TDA8706AM/C3	935260792118	RFS	DN49
TDA8706AM/C3	935260792518	RFS	DN49
TDA8783HL/C4	935266803118	RFS	DN48
TDA8783HL/C4	935266803151	RFS	DN48
TDA8784HL/C4	935266802118	RFS	DN48
TDA8784HL/C4	935266802151	RFS	DN48
TDA8784HL/C4	935266802157	RFS	DN48
TDA8784HL/C4	935266802518	RFS	DN48
VP22224A6	935276105557	RFS	DN62
VY22454A3	935275645026	CQS	DN62
VY22545-2	935273867557	RFS	DN58
VY22545-2	935273867557	RFS	DN58
VY22575-2	935276007557	RFS	DN62
VY22658-3	935284664026	RFS	DN62

NXP Semiconductors
Product Discontinuation DN64
Exhibit B - Product Reactivation List and Clarification Notice on Previously
Discontinued Products

June 30, 2009

B. Clarification on Replacement Parts

b.1 We introduced the P89CV51RX2 family version as replacement family as the previous proposed replacement family for the 8-bit Flash microcontrollers - the so called P89C51RX2 family appeared to have a pin to pin incompatibility issue.

Discontinued Part	Dropinreplacement	Cost attractive replacement	Discontinued on DN#
P89C51RA2BBD/01	P89CV51RB2BBC	P89V51RB2BBC	DN57
P89C51RB2BA/01	P89CV51RB2FA	P89V51RB2FA	DN57
P89C51RB2BBD/01	P89CV51RB2BBC	P89V51RB2BBC	DN57
P89C51RC2BA/01	P89CV51RC2FA	P89V51RC2FA	DN57
P89C51RC2BBD/01	P89CV51RC2FBC	P89V51RC2FBC	DN57
P89C51RC2BN/01		P89V51RC2FN	DN57
P89C51RC2FA/01	P89CV51RC2FA	P89V51RC2FA	DN57
P89C51RC2FBD/01	P89CV51RC2FBC	P89V51RC2FBC	DN57
P89C51RD2BA/01	P89CV51RD2FA	P89V51RD2FA	DN57
P89C51RD2BBD/01	P89CV51RD2FBC	P89V51RD2FBC	DN57
P89C51RD2BN/01		P89V51RD2BN	DN57
P89C51RD2FA/01	P89CV51RD2FA	P89V51RD2FA	DN57
P89C51RD2FN/01		P89V51RD2FN	DN57

b.2 Incorrect replacement part due to typo error

Discontinued Part	New Replacement Part	Discontinued on DN#
LPC2104BBD48	LPC2104FBD48/01	DN62