

NXP Semiconductors
Product Discontinuation Notice DN67

Exhibit B - Product Reactivation List and Clarification Notice on Previously Discontinued Products

December 15, 2010

A. Reactivation List

| Part Number | 12NC |
|----------------|--------------|
| 74HC165U | 933824420005 |
| BLC6G22-100 | 934059996112 |
| BLF6G27L-50BN | 934064686112 |
| BLF6G27L-50BN | 934064686118 |
| BLF6G27LS-50BN | 934064687112 |
| BLF6G27LS-50BN | 934064687118 |
| BUK205-50Y | 934041650118 |
| BUK2114-50SYTS | 934057284118 |
| BUK220-50Y | 934055403118 |
| OH201 | 934055424115 |
| OH201/S | 934059191115 |
| OH201/V | 934060021115 |
| OH202 | 934055425115 |
| OH203 | 934055426115 |
| OH221 | 934056680115 |
| OH222 | 934056681115 |
| OH223/M | 934058476115 |
| OP565 | 934057292005 |
| PH2925U | 934057828115 |
| PHD101NQ03LT | 934057029118 |
| TDA8783HL/C5 | 935277226151 |
| TDA8790M/C1 | 935201160118 |

B. Clarification on Previously Discontinued Products.

b.1 Incorrect Replacement Part

| Discontinued Part | New Replacement Part | Discontinued on DN# |
|-------------------|----------------------|---------------------|
| TDA8569Q/N2/S420C | TDA8569Q/N2S/S422 | DN64 |
| N74F112N | SN74F112N | DN66 |

b.2 Incorrect PCN year reflected on Customer Comments

| Discontinued Part | New Comment | Discontinued on DN# |
|-------------------|---|---------------------|
| PCA9512ADP/S900 | Limited Availability. Refer to PCN 2009040101 dated April 24, 2009. | DN65 |
| PCA9541D/03/S903 | Non-Manufacturable. Refer to PCN 2009040101 dated April 24, 2009. | DN65 |
| PCA9541PW/01/S903 | Non-Manufacturable. Refer to PCN 2009040101 dated April 24, 2009. | DN65 |
| PCA9541PW/03/S903 | Non-Manufacturable. Refer to PCN 2009040101 dated April 24, 2009. | DN65 |