

**"Philips Caen Fire Special Product Discontinuation Notice Number DN-51A Addendum"  
 Identified Caen Plant Previously Discontinued Products  
 Revised, Consolidated List  
 (Exhibit B-1)  
 March 12, 2004**

"THE BELOW LISTED PHILIPS' PART TYPES HAVE BEEN IDENTIFIED AS BEING ON A PREVIOUS PHILIPS' DISCONTINUED PRODUCT NOTICE AND ARE AFFECTED BY THE CAEN FIRE. AS SUCH, IF THESE PART TYPES ARE STILL ACTIVE AS: (a) STILL COMPLETING A FINAL DISCONTINUED PRODUCTS NOTICE CYCLE, OR (B) HAVING BEEN RE-ACTIVATED FROM A PRIOR DISCONTINUED PRODUCT STATUS AND THEIR LAST TIME SUPPLY CONDITIONS MAY HAVE BEEN SIGNIFICANTLY AFFECTED DUE TO THE CAEN FIRE CIRCUMSTANCES. PHILIPS SEMECONDUCTORS' CUSTOMERS NEED TO IMMEDIATELY VERIFY THE CURRENT PRODUCT AVAILABILITY CONDITIONS FOR THESE PRODUCTS WITH THEIR LOCAL ACCOUNT OR SALES MANAGERS. REFER TO PAGE 2 OF THE DN51 ORIGINAL NOTICE LETTER OR TO THE DN-51A ADDENDUM LETTER DATED MARCH 12, 2004 FOR FURTHER INFORMATION."

A. THIS SECTION LISTS ADDITIONAL NEW PARTS INFORMATION FOR PHILIPS' PREVIOUSLY AFFECTED OR DISCONTINUED THAT WERE NOT ON THE ORIGINAL EXHIBIT B TO DN-51 NOTICE DATED FEBRUARY 20, 2004.

Product Type	NC12	Basic Type	Business Line_Description	Main Article Group	Philips Package Type Description	Customer Comments
LM431ACMD	935242980118	None Noted	Linear industrial	R79	None Noted	no supply and no possibility of further Philips manufacture due to Caen fire
LM431ACMD	935242980112	None Noted	Linear industrial	R79	None Noted	no supply and no possibility of further Philips manufacture due to Caen fire
TL431ACD	935242960112	None Noted	Linear industrial	R79	None Noted	no supply and no possibility of further Philips manufacture due to Caen fire
TL431ACD	935242960118	None Noted	Linear industrial	R79	None Noted	no supply and no possibility of further Philips manufacture due to Caen fire
TL431ACD5	935271049115	None Noted	adjustable prec shunt regulator	R79	None Noted	no supply and no possibility of further Philips manufacture due to Caen fire
TL431ACPN	935243010112	None Noted	Linear industrial	R79	None Noted	no supply and no possibility of further Philips manufacture due to Caen fire
TL431AID	935242970118	None Noted	Linear industrial	R79	None Noted	no supply and no possibility of further Philips manufacture due to Caen fire
TL431AID	935242970112	None Noted	Linear industrial	R79	None Noted	no supply and no possibility of further Philips manufacture due to Caen fire
TL431AID5	935271050115	None Noted	adjustable prec shunt regulator	R79	None Noted	no supply and no possibility of further Philips manufacture due to Caen fire
TL431AIPN	935243020112	None Noted	Linear industrial	R79	None Noted	no supply and no possibility of further Philips manufacture due to Caen fire
TL431CD	935242940112	None Noted	Linear industrial	R79	None Noted	no supply and no possibility of further Philips manufacture due to Caen fire
TL431CD	935242940118	None Noted	Linear industrial	R79	None Noted	no supply and no possibility of further Philips manufacture due to Caen fire
TL431CD5	935271047115	None Noted	adjustable prec shunt regulator	R79	None Noted	no supply and no possibility of further Philips manufacture due to Caen fire
TL431CPN	935242990112	None Noted	Linear industrial	R79	None Noted	no supply and no possibility of further Philips manufacture due to Caen fire
TL431ID	935242950112	None Noted	Linear industrial	R79	None Noted	no supply and no possibility of further Philips manufacture due to Caen fire

**"Philips Caen Fire Special Product Discontinuation Notice Number DN-51A Addendum"**  
**Identified Caen Plant Previously Discontinued Products**  
**Revised, Consolidated List**  
**(Exhibit B-1)**  
**March 12, 2004**

Product Type	NC12	Basic Type	Business Line Description	Main Article Group	Philips Package Type Description	Customer Comments
TL431ID	935242950118	None Noted	Linear industrial	R79	None Noted	no supply and no possibility of further Philips manufacture due to Caen fire
TL431ID5	935271048115	None Noted	adjustable prec shunt regulator	R79	None Noted	no supply and no possibility of further Philips manufacture due to Caen fire
TL431IPN	935243000112	None Noted	Linear industrial	R79	None Noted	no supply and no possibility of further Philips manufacture due to Caen fire
TDA5140A/C1	933998200112	None Noted	Brushless DC motor driver	R79	None Noted	replacement TDA5140AT after August'04
TDA5141AT/C3	935067810112	None Noted	VCR motor control	R79	None Noted	replacement TDA5140AT after August'04
TDA5141AT/C3	935067810118	None Noted	VCR motor control	R79	None Noted	replacement TDA5140AT after August'04
TDA5142T/C2	935079220112	None Noted	HDD motor control	R79	None Noted	replacement TDA5140AT after August'04
TDA5142T/C2	935079220118	None Noted	HDD motor control	R79	None Noted	replacement TDA5140AT after August'04
TDA5145/C3	935067860112	None Noted	Brushless DC motor driver	R79	None Noted	replacement TDA5145T after August'04
TDA5241/C1	935211440112	None Noted	VCR motor control	R79	None Noted	replacement TDA5240T after August'04
TDA5241T/C1	935261039112	None Noted	VCR motor control	R79	None Noted	replacement TDA5240T after August'04
TDA5241T/C1	935261039118	None Noted	VCR motor control	R79	None Noted	replacement TDA5240T after August'04
TDF5242T/C1	935178120112	None Noted	VCR motor control	R79	None Noted	replacement TDA5240T after August'04
TDF5242T/C1	935178120118	None Noted	VCR motor control	R79	None Noted	replacement TDA5240T after August'04
TEA1110A/C1	935229750112	None Noted	BIPOLAR ANALOG TELECOM (CAEN)	R42	None Noted	All package types transferred to another Philips location. Refer to CPCN #200403009 issued 3/2/04.Consult Marketing.
TEA1110AT/C1	935229760512	None Noted	BIPOLAR ANALOG TELECOM (CAEN)	R42	None Noted	All package types transferred to another Philips location. Refer to CPCN #200403009 issued 3/2/04.Consult Marketing.
TEA1110AT/C1	935229760518	None Noted	BIPOLAR ANALOG TELECOM (CAEN)	R42	None Noted	All package types transferred to another Philips location. Refer to CPCN #200403009 issued 3/2/04.Consult Marketing.
TEA1110AUH/C1	935264051005	None Noted	LOW VOLT VERSATILE TEL TRANS CIRC.	R42	None Noted	All package types transferred to another Philips location. Refer to CPCN #200403009 issued 3/2/04.Consult Marketing.
TEA1098ATV/C1	935263491112	None Noted	SPEECH & HANDFREE IC	R42	None Noted	All package types transferred to another Philips location. Refer to CPCN #200403009 issued 3/2/04.Consult Marketing.
TEA1098ATV/C1	935263491118	None Noted	SPEECH & HANDFREE IC	R42	None Noted	All package types transferred to another Philips location. Refer to CPCN #200403009 issued 3/2/04.Consult Marketing.
TEA1098AUH/C1	935267472005	None Noted	SPEECH & HANDFREE IC	R42	None Noted	All package types transferred to another Philips location. Refer to CPCN #200403009 issued 3/2/04.Consult Marketing.
TEA1098TV/C2	935263449112	None Noted	BIPOLAR ANALOG TELECOM (CAEN)	R42	None Noted	All package types transferred to another Philips location. Refer to CPCN #200403009 issued 3/2/04.Consult Marketing.
TEA1098TV/C2	935263449118	None Noted	BIPOLAR ANALOG TELECOM (CAEN)	R42	None Noted	All package types transferred to another Philips location. Refer to CPCN #200403009 issued 3/2/04.Consult Marketing.

**"Philips Caen Fire Special Product Discontinuation Notice Number DN-51A Addendum"**  
**Identified Caen Plant Previously Discontinued Products**  
**Revised, Consolidated List**  
**(Exhibit B-1)**  
**March 12, 2004**

Product Type	NC12	Basic Type	Business Line Description	Main Article Group	Philips Package Type Description	Customer Comments
TEA1111AT/C1	935262584512	None Noted	SPEECH CIRCUIT WITH DIALLER INTERF.	R42	None Noted	Transferred to another Philips location. Refer to CPCN #200403009 issued 3/2/04. Consult Marketing.
TEA1111AT/C1	935262584518	None Noted	SPEECH CIRCUIT WITH DIALLER INTERF.	R42	None Noted	Transferred to another Philips location. Refer to CPCN #200403009 issued 3/2/04. Consult Marketing.
TEA1114AT/C2	935263380512	None Noted	BIPOLAR ANALOG TELECOM (CAEN)	R42	None Noted	Transferred to another Philips location. Refer to CPCN #200403009 issued 3/2/04. Consult Marketing.
TEA1114AT/C2	935263380518	None Noted	BIPOLAR ANALOG TELECOM (CAEN)	R42	None Noted	Transferred to another Philips location. Refer to CPCN #200403009 issued 3/2/04. Consult Marketing.
LM2901DH	935271896118	None Noted	QUAD VOLTAGE COMPARATOR	R13	None Noted	Replacement ON Semi: LM2901VDTBR2. No possibility of further Philips manufacture due to CAEN fire.
NE5521N	933791040602	None Noted	LINEAR INDUSTRIAL	R13	None Noted	No replacement available. No possibility of further Philips manufacture due to CAEN fire.
SA556N	933925160602	None Noted	LINEAR INDUSTRIAL	R13	None Noted	Replacement ST: SA556N. No possibility of further Philips manufacture due to CAEN fire.
ALP008M/C1	935182900118	None Noted	STUBILO DM	R25	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.
TDA5633M/C1	935084970118	None Noted	STUBILO DM	R25	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.
TDA5736T/C1/M1	935261948118	None Noted	STUBILO DM	R25	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.
TDA5737M/C1/M1	935261636118	None Noted	STUBILO DM	R25	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.
TDA6403M/C3	935262628118	None Noted	STUBILO TM	R25	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.
TDA6405ATS/C1	935261037112	None Noted	STUBILO DM	R25	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.
TDA6405ATS/C1	935261037118	None Noted	STUBILO DM	R25	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.
TDA6405ATS/C1	935261037512	None Noted	STUBILO DM	R25	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.
TDA6405ATS/C1	935261037518	None Noted	STUBILO DM	R25	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.
TDA6405TS/C1	935251700112	None Noted	STUBILO DM	R25	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.
TDA6405TS/C1	935251700118	None Noted	STUBILO DM	R25	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.
TDA6405TS/C1	935251700512	None Noted	STUBILO DM	R25	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.
TDA6405TS/C1	935251700518	None Noted	STUBILO DM	R25	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.
TDA8012M/C1	935071280118	None Noted	STUBILO DM	R25	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.
TDA8012M/C1/S1	935212740118	None Noted	STUBILO DM	R25	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.
TDA8722M/C3	935224930112	None Noted	STUBILO DM	R25	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.
TDA8722M/C3	935224930118	None Noted	STUBILO DM	R25	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.
TDA8722T/C2	935184370112	None Noted	STUBILO DM	R25	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.
TDA8722T/C2	935184370118	None Noted	STUBILO DM	R25	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.
TDA8722T/C3	935224990112	None Noted	STUBILO DM	R25	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.

**"Philips Caen Fire Special Product Discontinuation Notice Number DN-51A Addendum"**  
**Identified Caen Plant Previously Discontinued Products**  
**Revised, Consolidated List**  
**(Exhibit B-1)**  
**March 12, 2004**

Product Type	NC12	Basic Type	Business Line_Description	Main Article Group	Philips Package Type Description	Customer Comments
TDA8722T/C3	935182900118	None Noted	STUBILO DM	R25	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.
TDA8822M/C1	935221010512	None Noted	STUBILO TM	R25	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.
TDA8822M/C1	935221010518	None Noted	STUBILO TM	R25	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.
TSA5515T/C1	935037130512	None Noted	STUBILO DM	R25	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.
TSA5515T/C1	935037130518	None Noted	STUBILO DM	R25	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.
TSA5526DTS/C1	935260349118	None Noted	STUBILO TM	R25	None Noted	Limited supply, No possibility of further Philips manufacture beyond remaining available stock, due to CAEN fire. Consult Marketing.

**B. THE FOLLOWING CAEN PART TYPES WERE LISTED ON PHILIPS DN-51 EXHIBIT B DATED FEBRUARY 20, 2004 AS "PREVIOUSLY DISCONTINUED PART TYPES". THEY ARE NOW BEING LISTED AGAIN FOR INFORMATION TO PHILIPS' CUSTOMERS TO INDICATE THAT PREVIOUS DISCONTINUED PRODUCT LAST TIME BUY AVAILABILITY CONDITIONS MAY HAVE CHANGED DUE TO THE CAEN FIRE. REFER TO PHILIPS' PRODUCT DISCONTINUATION NOTICE NUMBER DN-51 TERMS AND CONDITIONS FOR DETAILS.**

Product Type	NC12	Basic Type	Business Line_Description	Main Article Group	Philips Package Type Description	Customer Comments
CD8276D	935116510118	CD8276D	STANDARD IC'S	R13	SO16	None Noted
MC1408-8N/CD8147	935116150112	MC1408-8N	STANDARD IC'S	R13	DIP16	None Noted
NE532D/CD8266	935116470118	NE532D	STANDARD IC'S	R13	SO8	None Noted
NE555N/CJ748	933467760112	NE555N	STANDARD IC'S	R13	DIP8	None Noted
SA5230D/CD8380	935184550112	SA5230D	STANDARD IC'S	R13	SO8	None Noted
SA5230D/CD8380	935184550118	SA5230D	STANDARD IC'S	R13	SO8	None Noted
SA5521D	933842760512	SA5521D	STANDARD IC'S	R13	SO16	None Noted
SA5521D	933842760518	SA5521D	STANDARD IC'S	R13	SO16	None Noted
XAU2903CK	935230500026	XAU2903CK	STANDARD IC'S	R13	UNCASED	None Noted
XN5230CK	935045540602	XN5230CK	STANDARD IC'S	R13	UNCASED	None Noted
XNE5539CK	935146190026	XNE5539CK	STANDARD IC'S	R13	UNCASED	None Noted
ALP008M/C1	935182900118	ALP008M	MAINSTR TV SOLUTIONS	R25	SSOP20	None Noted
MTI3000T/C1	935071300118	MTI3000T	MAINSTR TV SOLUTIONS	R25	SO20	None Noted
OM5188M/C1	935233380118	OM5188M	MAINSTR TV SOLUTIONS	R25	SSOP24	None Noted

**"Philips Caen Fire Special Product Discontinuation Notice Number DN-51A Addendum"**  
**Identified Caen Plant Previously Discontinued Products**  
**Revised, Consolidated List**  
**(Exhibit B-1)**  
**March 12, 2004**

Product Type	NC12	Basic Type	Business Line Description	Main Article Group	Philips Package Type Description	Customer Comments
TDA5330T/C5	935032850112	TDA5330T	MAINSTR TV SOLUTIONS	R25	SO28	None Noted
TDA5330T/C5	935032850118	TDA5330T	MAINSTR TV SOLUTIONS	R25	SO28	None Noted
TDA5332T/C5	935032920118	TDA5332T	MAINSTR TV SOLUTIONS	R25	SO20	None Noted
TDA5630M/C2	935056180112	TDA5630M	MAINSTR TV SOLUTIONS	R25	SSOP20	None Noted
TDA5630M/C2	935056180118	TDA5630M	MAINSTR TV SOLUTIONS	R25	SSOP20	None Noted
TDA5633M/C1	935084970118	TDA5633M	MAINSTR TV SOLUTIONS	R25	SSOP20	None Noted
TDA6403AM/C3	935262630118	TDA6403AM	MAINSTR TV SOLUTIONS	R25	SSOP28	None Noted
TDA6403M/C2	935261234518	TDA6403M	MAINSTR TV SOLUTIONS	R25	SSOP28	None Noted
TDA6403M/C3	935262628118	TDA6403M	MAINSTR TV SOLUTIONS	R25	SSOP28	None Noted
TDA6405ATS/C1	935261037118	TDA6405ATS	MAINSTR TV SOLUTIONS	R25	SSOP28	None Noted
TDA6405ATS/C1	935261037112	TDA6405ATS	MAINSTR TV SOLUTIONS	R25	SSOP28	None Noted
TDA6405TS/C1	935251700118	TDA6405TS	MAINSTR TV SOLUTIONS	R25	SSOP28	None Noted
TDA6405TS/C1	935251700112	TDA6405TS	MAINSTR TV SOLUTIONS	R25	SSOP28	None Noted
TDA8540/C2	935057490112	TDA8540	MAINSTR TV SOLUTIONS	R25	DIP20	None Noted
TDA8722M/C3	935224930118	TDA8722M	MAINSTR TV SOLUTIONS	R25	SSOP20	None Noted
TDA8722M/C3	935224930112	TDA8722M	MAINSTR TV SOLUTIONS	R25	SSOP20	None Noted
TDA8722T/C2	935184370118	TDA8722T	MAINSTR TV SOLUTIONS	R25	SO20	None Noted
TDA8722T/C3	935224990118	TDA8722T	MAINSTR TV SOLUTIONS	R25	SO20	None Noted
TDA8722T/C3	935224990112	TDA8722T	MAINSTR TV SOLUTIONS	R25	SO20	None Noted
TDA8735T/C1	935055610118	TDA8735T	MAINSTR TV SOLUTIONS	R25	SO16	None Noted
TDA8822M/C1	935221010118	TDA8822M	MAINSTR TV SOLUTIONS	R25	SSOP24	None Noted
TDA8822M/C1	935221010112	TDA8822M	MAINSTR TV SOLUTIONS	R25	SSOP24	None Noted
TSA5511/C4	935196640112	TSA5511	MAINSTR TV SOLUTIONS	R25	DIP18	None Noted
TSA5515T/C1	935037130512	TSA5515T	MAINSTR TV SOLUTIONS	R25	SO14	None Noted
TSA5526M/C2	935260883118	TSA5526M	MAINSTR TV SOLUTIONS	R25	SSOP16	None Noted
TEA1094AT/C2	935264478112	TEA1094AT	CORDLESS & IMAGING	R42	SO24	None Noted
TEA1112/C1	935206280112	TEA1112	CORDLESS & IMAGING	R42	DIP16	None Noted

**"Philips Caen Fire Special Product Discontinuation Notice Number DN-51A Addendum"**  
**Identified Caen Plant Previously Discontinued Products**  
**Revised, Consolidated List**  
**(Exhibit B-1)**  
**March 12, 2004**

Product Type	NC12	Basic Type	Business Line_Description	Main Article Group	Philips Package Type Description	Customer Comments
TEA1094AT/C2	935264478112	TEA1094AT	CORDLESS & IMAGING	R42	SO24	None Noted
TEA1112/C1	935206280112	TEA1112	CORDLESS & IMAGING	R42	DIP16	None Noted
TEA1112/C1	935206280112	TEA1112	CORDLESS & IMAGING	R42	DIP16	None Noted
TEA1112T/C1	935206290112	TEA1112T	CORDLESS & IMAGING	R42	SO16	None Noted
TEA1113T/C1	935211140518	TEA1113T	CORDLESS & IMAGING	R42	SO16	None Noted
TEA1113T/C1	935211140512	TEA1113T	CORDLESS & IMAGING	R42	SO16	None Noted
UAA3515AHL/C2	935270885118	UAA3515AHL	CORDLESS & IMAGING	R42	LQFP64	None Noted
UAA3515AHL/C2	935270885118	UAA3515AHL	CORDLESS & IMAGING	R42	LQFP64	None Noted
UAA3515BUH/C2	935270888005	UAA3515BUH	CORDLESS & IMAGING	R42	UNCASED	None Noted
UAA3515BUH/C2	935270888005	UAA3515BUH	CORDLESS & IMAGING	R42	UNCASED	None Noted
UAA3515UH/C2	935270886005	UAA3515UH	CORDLESS & IMAGING	R42	UNCASED	None Noted
UAA3515UH/C2	935270886005	UAA3515UH	CORDLESS & IMAGING	R42	UNCASED	None Noted
UAA3517BUH/C2	935271711005	UAA3517BUH	CORDLESS & IMAGING	R42	UNCASED	None Noted
UAA3517BUH/C2	935271711005	UAA3517BUH	CORDLESS & IMAGING	R42	UNCASED	None Noted
UAA3517BUH/C3	935272393005	UAA3517BUH	CORDLESS & IMAGING	R42	UNCASED	None Noted
UAA3517BUH/C3	935272393005	UAA3517BUH	CORDLESS & IMAGING	R42	UNCASED	None Noted
UAA3519AHL/C2	935270891118	UAA3519AHL	CORDLESS & IMAGING	R42	LQFP64	None Noted
UAA3519AHL/C2	935270891118	UAA3519AHL	CORDLESS & IMAGING	R42	LQFP64	None Noted
UAA3519AUH/C2	935271942005	UAA3519AUH	CORDLESS & IMAGING	R42	UNCASED	None Noted
UAA3519AUH/C2	935271942005	UAA3519AUH	CORDLESS & IMAGING	R42	UNCASED	None Noted
TDA8001AT/C1	935181110118	TDA8001AT	IDENTIFICATION	R63	SO28	None Noted
TDA8001AT/C1	935181110112	TDA8001AT	IDENTIFICATION	R63	SO28	None Noted
TDA8001T/C1	935181100118	TDA8001T	IDENTIFICATION	R63	SO28	None Noted
TDA8001T/C1	935181100112	TDA8001T	IDENTIFICATION	R63	SO28	None Noted
TDA8003TS/C1	935260674518	TDA8003TS	IDENTIFICATION	R63	SSOP24	None Noted
TDA8003TS/C2	935263632118	TDA8003TS	IDENTIFICATION	R63	SSOP24	None Noted