

**REACTIVATION REPORT**  
**Exhibit B - DN 57**  
**June 30, 2006**

**This report covers parts re-activated December 1, 2005 to May 31, 2006.**

<b>Type Number</b>	<b>12NC</b>	<b>PREVIOUS DN</b>	<b>PreviousS tate</b>	<b>6TG</b>	<b>MAG</b>	<b>Current State</b>
74LVTH244ADB	9352 620 70118	DN41	WIT	565433	R07	RFS
74LVTH244APW	9352 620 71118	DN41	WIT	565453	R07	RFS
BTI38X-600G	9340 232 20127	DN40			R70	RFS
BYV29-600	9340 558 95127	DN48	WIT	9663Z9	R72	RFS
OQ0256HP/N3	9352 634 22557	DN56	DOD	452988	R77	RFS
OQ0257HP/N2	9352 218 10557	DN56	DOD	452979	R77	RFS
OQ0258HP/N2	9352 218 20557	DN56	DOD	452980	R77	RFS
OQ0260HL/N3	9352 632 58557	DN56	DOD	452986	R77	RFS
P80C51RA+4A/G	9352 769 64512	DN56	DOD	837241	R05	RFS
P80C51SFPN/CV5182	9352 665 95112	DN44	DOD	837210	R05	RFS
P83C557E2EFB/208	9352 690 75518	DN55	DOD	8372N2	R05	RFS
P83C575EHPN/CV5832	9352 701 65112	DN46	WIT	8372B0	R05	RFS
P87LPC762BDH/G	9352 777 43512	DN56	DOD	837418	R05	RFS
P87LPC764BD/G	9352 777 82512	DN56	DOD	837425	R05	RFS
P89LPC932A1FDH/G	9352 803 63512	DN56	DOD	837599	R05	RFS
PCF8811MU/2DA/1	9352 704 36026	DN56	DOD	410278	R15	RFS
SAA7722H/N306/S420	9352 699 56518	DN54	WIT	510511	R32	RFS
VP22221-2	9352 676 43557	DN49	WIT	508210	R67	RFS