

NXP Semiconductors
Product Discontinuation Notice DN67A
Exhibit A-1
January 31, 2011

SEE DN67A NOTICE LETTER FOR APPLICABLE LAST TIME BUY TERMS, CONDITIONS AND CODE DEFINITIONS FOR THESE DISCONTINUED PRODUCTS.
FOR ADDED INFORMATION, REFER TO NXP WEB-SITE "<http://www.nxp.com/products/eol/>"

TYPE CODE:

T = Type number fully withdrawn
N = Part type package only withdrawn

SOURCE CODE

C = Customer Specific Product
M = Multiple Source Product
S = Sole Source Product

AVAILABILITY CODE:

1 = Non-availability. No last time buy possible
2 = Limited Availability (check with your usual sales contact)
3 = Standard Availability

Type Number	NXP Type Number	Description	12NC	Discontinuation Type Code	Source Code	Availability Code	Last Time Buy Date	Last Time Delivery Date	Replacement Part	Customer Comments
BUK220-50Y	BUK220-50Y118	TOFET	934055403118	T	M	3	31-jul-11	31-jan-12	None	Standard End of Life.
BUK9640-100A/C	BUK9640-100A/C,118	D2PAK	934060689118	N	C	1	31-jan-11	31-jan-11	BUK9640-100A/C1	Non-Manufacturable. Refer to PCN 200809011F dated September 17, 2008.
P89CV51RB2FA	P89CV51RB2FA,512		935284111512	T	M	2	30-jun-11	30-sep-11	See Comments	Limited Availability. NXP suggests 32-bit ARM Cortex-M0 family for 8-bit replacement.
P89CV51RB2FBC	P89CV51RB2FBC,557		935284179557	T	M	2	30-jun-11	30-sep-11	See Comments	Limited Availability. NXP suggests 32-bit ARM Cortex-M0 family for 8-bit replacement.
P89LPC901FD	P89LPC901FD,112		935273904112	T	S	2	30-jun-11	30-sep-11	See Comments	Limited Availability. NXP suggests 32-bit ARM Cortex-M0 family for 8-bit replacement.
P89LPC901FN	P89LPC901FN,129		935273898129	T	S	2	30-jun-11	30-sep-11	See Comments	Limited Availability. NXP suggests 32-bit ARM Cortex-M0 family for 8-bit replacement.
P89LPC902FD	P89LPC902FD,112		935273905112	T	S	2	30-jun-11	30-sep-11	See Comments	Limited Availability. NXP suggests 32-bit ARM Cortex-M0 family for 8-bit replacement.
P89LPC902FN	P89LPC902FN,129		935273899129	T	S	2	30-jun-11	30-sep-11	See Comments	Limited Availability. NXP suggests 32-bit ARM Cortex-M0 family for 8-bit replacement.
P89LPC903FD	P89LPC903FD,112		935273906112	T	S	2	30-jun-11	30-sep-11	See Comments	Limited Availability. NXP suggests 32-bit ARM Cortex-M0 family for 8-bit replacement.
P89LPC9103FTK	P89LPC9103FTK,115		935278503115	T	S	2	30-jun-11	30-sep-11	See Comments	Limited Availability. NXP suggests 32-bit ARM Cortex-M0 family for 8-bit replacement.
P89LPC9107FDH	P89LPC9107FDH,129		935278497129	T	S	2	30-jun-11	30-sep-11	See Comments	Limited Availability. NXP suggests 32-bit ARM Cortex-M0 family for 8-bit replacement.
P89LPC921FDH/CP3261	P89LPC921FDH/CP326		935288388512	N	C	2	30-jun-11	30-sep-11	See Comments	Limited Availability. NXP suggests 32-bit ARM Cortex-M0 family for 8-bit replacement.
P89LPC931FDH/CP3243	P89LPC931FDH/CP324		935282323112	N	C	2	30-jun-11	30-sep-11	See Comments	Limited Availability. NXP suggests 32-bit ARM Cortex-M0 family for 8-bit replacement.
P89LPC9401FBD	P89LPC9401FBD,551		935278626551	T	S	2	30-jun-11	30-sep-11	See Comments	Limited Availability. NXP suggests 32-bit ARM Cortex-M0 family for 8-bit replacement.
P89LPC9401FBD	P89LPC9401FBD,551		935278626557	T	S	2	30-jun-11	30-sep-11	See Comments	Limited Availability. NXP suggests 32-bit ARM Cortex-M0 family for 8-bit replacement.
P89LPC9402FBD	P89LPC9402FBD,557		935288631557	T	S	2	30-jun-11	30-sep-11	See Comments	Limited Availability. NXP suggests 32-bit ARM Cortex-M0 family for 8-bit replacement.

NXP Semiconductors
Product Discontinuation Notice DN67A
Exhibit A-1
January 31, 2011

P89LPC9408FBD	P89LPC9408FBD,557		935280583557	T	S	2	30-jun-11	30-sep-11	See Comments	Limited Availability. NXP suggests 32-bit ARM Cortex-M0 family for 8-bit replacement.
P89LV51RB2BA	P89LV51RB2BA,512		935277744512	T	M	2	30-jun-11	30-sep-11	See Comments	Limited Availability. NXP suggests 32-bit ARM Cortex-M0 family for 8-bit replacement.
P89V51RB2BBC	P89V51RB2BBC,557		935277723557	T	M	2	30-jun-11	30-sep-11	See Comments	Limited Availability. NXP suggests 32-bit ARM Cortex-M0 family for 8-bit replacement.
P89V51RB2FA	P89V51RB2FA,529		935278706529	T	M	2	30-jun-11	30-sep-11	See Comments	Limited Availability. NXP suggests 32-bit ARM Cortex-M0 family for 8-bit replacement.
P89V51RB2FN	P89V51RB2FN,112		935278707112	T	M	2	30-jun-11	30-sep-11	See Comments	Limited Availability. NXP suggests 32-bit ARM Cortex-M0 family for 8-bit replacement.
P89V52X2FA	P89V52X2FA,512		935282528512	T	M	2	30-jun-11	30-sep-11	See Comments	Limited Availability. NXP suggests 32-bit ARM Cortex-M0 family for 8-bit replacement.
P89V52X2FBD	P89V52X2FBD,157		935282529157	T	M	2	30-jun-11	30-sep-11	See Comments	Limited Availability. NXP suggests 32-bit ARM Cortex-M0 family for 8-bit replacement.
P89V52X2FN	P89V52X2FN,112		935282526112	T	M	2	30-jun-11	30-sep-11	See Comments	Limited Availability. NXP suggests 32-bit ARM Cortex-M0 family for 8-bit replacement.
P89V660FA	P89V660FA,512		935280828512	T	M	2	30-jun-11	30-sep-11	See Comments	Limited Availability. NXP suggests 32-bit ARM Cortex-M0 family for 8-bit replacement.
P89V660FBC	P89V660FBC,557		935280829557	T	M	2	30-jun-11	30-sep-11	See Comments	Limited Availability. NXP suggests 32-bit ARM Cortex-M0 family for 8-bit replacement.
PCF8576DH/2	PCF8576DH/2518	LCD SEGMENT DRIVER	935276165518	T	S	2	30-jun-11	31-dec-11	PCF85176H/1	Limited Availability. Subpackage is phasing out.
SAF7730HV/N116	SAF7730HV/N116,518		935275674518	N	S	3	31-okt-11	31-jan-12	SAF7730HV/N116D	Standard End of Life. Bond wire change only. Refer to PCN# 201004013F dated August 2, 2010.
SAF7730HV/N116	SAF7730HV/N116,557		935275674557	N	S	3	31-okt-11	31-jan-12	SAF7730HV/N116D	Standard End of Life. Bond wire change only. Refer to PCN# 201004013F dated August 2, 2010.
SAF7730HV/N212	SAF7730HV/N212,518		935277036518	N	C	3	31-okt-11	31-jan-12	SAF7730HV/N212D	Standard End of Life. Bond wire change only. Refer to PCN# 201004013F dated August 2, 2010.
SAF7730HV/N212	SAF7730HV/N212,557		935277036557	N	C	3	31-okt-11	31-jan-12	SAF7730HV/N212D	Standard End of Life. Bond wire change only. Refer to PCN# 201004013F dated August 2, 2010.
SAF7730HV/N217	SAF7730HV/N217,557		935276405557	N	S	3	31-okt-11	31-jan-12	SAF7730HV/N217D	Standard End of Life. Bond wire change only. Refer to PCN# 201004013F dated August 2, 2010.
SAF7730HV/N217	SAF7730HV/N217,518		935276405518	N	S	3	31-okt-11	31-jan-12	SAF7730HV/N217D	Standard End of Life. Bond wire change only. Refer to PCN# 201004013F dated August 2, 2010.
SAF7730HV/N219	SAF7730HV/N219,518		935277736518	N	C	3	31-okt-11	31-jan-12	SAF7730HV/N219D	Standard End of Life. Bond wire change only. Refer to PCN# 201004013F dated August 2, 2010.
SAF7730HV/N219	SAF7730HV/N219,557		935277736557	N	C	3	31-okt-11	31-jan-12	SAF7730HV/N219D	Standard End of Life. Bond wire change only. Refer to PCN# 201004013F dated August 2, 2010.
SAF7730HV/N220	SAF7730HV/N220,518		935277735518	N	C	3	31-okt-11	31-jan-12	SAF7730HV/N220D	Standard End of Life. Bond wire change only. Refer to PCN# 201004013F dated August 2, 2010.
SAF7730HV/N220	SAF7730HV/N220,557		935277735557	N	C	3	31-okt-11	31-jan-12	SAF7730HV/N220D	Standard End of Life. Bond wire change only. Refer to PCN# 201004013F dated August 2, 2010.
SAF7730HV/N221	SAF7730HV/N221,518		935277737518	N	C	3	31-okt-11	31-jan-12	SAF7730HV/N221D	Standard End of Life. Bond wire change only. Refer to PCN# 201004013F dated August 2, 2010.
SAF7730HV/N221	SAF7730HV/N221,557		935277737557	N	C	3	31-okt-11	31-jan-12	SAF7730HV/N221D	Standard End of Life. Bond wire change only. Refer to PCN# 201004013F dated August 2, 2010.
SAF7730HV/N223	SAF7730HV/N223,518		935279656518	N	C	3	31-okt-11	31-jan-12	SAF7730HV/N223D	Standard End of Life. Bond wire change only. Refer to PCN# 201004013F dated August 2, 2010.
SAF7730HV/N223	SAF7730HV/N223,557		935279656557	N	C	3	31-okt-11	31-jan-12	SAF7730HV/N223D	Standard End of Life. Bond wire change only. Refer to PCN# 201004013F dated August 2, 2010.

NXP Semiconductors
Product Discontinuation Notice DN67A
Exhibit A-1
January 31, 2011

SAF7730HV/N224	SAF7730HV/N224,518		935277038518	N	S	3	31-okt-11	31-jan-12	SAF7730HV/N224D	Standard End of Life. Bond wire change only. Refer to PCN# 201004013F dated August 2, 2010.
SAF7730HV/N224	SAF7730HV/N224,557		935277038557	N	S	3	31-okt-11	31-jan-12	SAF7730HV/N224D	Standard End of Life. Bond wire change only. Refer to PCN# 201004013F dated August 2, 2010.
SAF7730HV/N224/S1	SAF7730HV/N224/S1,		935282855557	N	C	3	31-okt-11	31-jan-12	SAF7730HV/N224D/S1	Standard End of Life. Bond wire change only. Refer to PCN# 201004013F dated August 2, 2010.
SAF7730HV/N226	SAF7730HV/N226,557		935277119557	N	C	3	31-okt-11	31-jan-12	SAF7730HV/N226D	Standard End of Life. Bond wire change only. Refer to PCN# 201004013F dated August 2, 2010.
SAF7730HV/N226	SAF7730HV/N226,518		935277119518	N	C	3	31-okt-11	31-jan-12	SAF7730HV/N226D	Standard End of Life. Bond wire change only. Refer to PCN# 201004013F dated August 2, 2010.
SAF7730HV/N226/S30	SAF7730HV/N226/S30		935285351518	N	C	3	31-okt-11	31-jan-12	SAF7730HV/N226D/S30	Standard End of Life. Bond wire change only. Refer to PCN# 201004013F dated August 2, 2010.
SAF7730HV/N226/S30	SAF7730HV/N226/S30		935285351557	N	C	3	31-okt-11	31-jan-12	SAF7730HV/N226D/S30	Standard End of Life. Bond wire change only. Refer to PCN# 201004013F dated August 2, 2010.
SAF7730HV/N226/S31	SAF7730HV/N226/S31		935285352518	N	C	3	31-okt-11	31-jan-12	SAF7730HV/N226D/S31	Standard End of Life. Bond wire change only. Refer to PCN# 201004013F dated August 2, 2010.
SAF7730HV/N226/S31	SAF7730HV/N226/S31		935285352557	N	C	3	31-okt-11	31-jan-12	SAF7730HV/N226D/S31	Standard End of Life. Bond wire change only. Refer to PCN# 201004013F dated August 2, 2010.
SAF7730HV/N231	SAF7730HV/N231,518		935279876518	N	S	3	31-okt-11	31-jan-12	SAF7730HV/N231D	Standard End of Life. Bond wire change only. Refer to PCN# 201004013F dated August 2, 2010.
SAF7730HV/N231	SAF7730HV/N231,518		935279876557	N	S	3	31-okt-11	31-jan-12	SAF7730HV/N231D	Standard End of Life. Bond wire change only. Refer to PCN# 201004013F dated August 2, 2010.
SAF7730HV/N233	SAF7730HV/N233,518		935281255518	N	C	3	31-okt-11	31-jan-12	SAF7730HV/N233D	Standard End of Life. Bond wire change only. Refer to PCN# 201004013F dated August 2, 2010.
SAF7730HV/N233	SAF7730HV/N233,557		935281255557	N	C	3	31-okt-11	31-jan-12	SAF7730HV/N233D	Standard End of Life. Bond wire change only. Refer to PCN# 201004013F dated August 2, 2010.
SAF7730HV/N233/S30	SAF7730HV/N233/S30		935291139518	N	C	3	31-okt-11	31-jan-12	SAF7730HV/N233D/S30	Standard End of Life. Bond wire change only. Refer to PCN# 201004013F dated August 2, 2010.
SAF7730HV/N235	SAF7730HV/N235,557		935282864557	N	C	3	31-okt-11	31-jan-12	SAF7730HV/N235D	Standard End of Life. Bond wire change only. Refer to PCN# 201004013F dated August 2, 2010.
SAF7730HV/N235	SAF7730HV/N235,518		935282864518	N	C	3	31-okt-11	31-jan-12	SAF7730HV/N235D	Standard End of Life. Bond wire change only. Refer to PCN# 201004013F dated August 2, 2010.
SAF7730HV/N312	SAF7730HV/N312,518		935281532518	N	C	3	31-okt-11	31-jan-12	SAF7730HV/N312D	Standard End of Life. Bond wire change only. Refer to PCN# 201004013F dated August 2, 2010.
SAF7730HV/N312	SAF7730HV/N312,557		935281532557	N	C	3	31-okt-11	31-jan-12	SAF7730HV/N312D	Standard End of Life. Bond wire change only. Refer to PCN# 201004013F dated August 2, 2010.
SAF7730HV/N317	SAF7730HV/N317,518		935280688518	N	C	3	31-okt-11	31-jan-12	SAF7730HV/N317D	Standard End of Life. Bond wire change only. Refer to PCN# 201004013F dated August 2, 2010.
SAF7730HV/N317	SAF7730HV/N317,557		935280688557	N	C	3	31-okt-11	31-jan-12	SAF7730HV/N317D	Standard End of Life. Bond wire change only. Refer to PCN# 201004013F dated August 2, 2010.
SAF7730HV/N317/S1	SAF7730HV/N317/S1,		935284267518	N	C	3	31-okt-11	31-jan-12	SAF7730HV/N317D/S1	Standard End of Life. Bond wire change only. Refer to PCN# 201004013F dated August 2, 2010.
SAF7730HV/N317/S1	SAF7730HV/N317/S1:		935284267557	N	C	3	31-okt-11	31-jan-12	SAF7730HV/N317D/S1	Standard End of Life. Bond wire change only. Refer to PCN# 201004013F dated August 2, 2010.
SAF7730HV/N322	SAF7730HV/N322,518		935281543518	N	C	3	31-okt-11	31-jan-12	SAF7730HV/N322D	Standard End of Life. Bond wire change only. Refer to PCN# 201004013F dated August 2, 2010.
SAF7730HV/N322	SAF7730HV/N322,557		935281543557	N	C	3	31-okt-11	31-jan-12	SAF7730HV/N322D	Standard End of Life. Bond wire change only. Refer to PCN# 201004013F dated August 2, 2010.

NXP Semiconductors
Product Discontinuation Notice DN67A
Exhibit A-1
January 31, 2011

SAF7730HV/N323	SAF7730HV/N323,518		935281533518	N	S	3	31-okt-11	31-jan-12	SAF7730HV/N323D	Standard End of Life. Bond wire change only. Refer to PCN# 201004013F dated August 2, 2010.
SAF7730HV/N323	SAF7730HV/N323,557		935281533557	N	S	3	31-okt-11	31-jan-12	SAF7730HV/N323D	Standard End of Life. Bond wire change only. Refer to PCN# 201004013F dated August 2, 2010.
SAF7730HV/N324	SAF7730HV/N324,518		935280687518	N	S	3	31-okt-11	31-jan-12	SAF7730HV/N324D	Standard End of Life. Bond wire change only. Refer to PCN# 201004013F dated August 2, 2010.
SAF7730HV/N324	SAF7730HV/N324,557		935280687557	N	S	3	31-okt-11	31-jan-12	SAF7730HV/N324D	Standard End of Life. Bond wire change only. Refer to PCN# 201004013F dated August 2, 2010.
SAF7730HV/N331	SAF7730HV/N331518		935281534518	N	S	3	31-okt-11	31-jan-12	SAF7730HV/N331D	Standard End of Life. Bond wire change only. Refer to PCN# 201004013F dated August 2, 2010.
SAF7730HV/N331	SAF7730HV/N331518		935281534557	N	S	3	31-okt-11	31-jan-12	SAF7730HV/N331D	Standard End of Life. Bond wire change only. Refer to PCN# 201004013F dated August 2, 2010.
SAF7730HV/N332	SAF7730HV/N332,518		935282255518	N	C	3	31-okt-11	31-jan-12	SAF7730HV/N332D	Standard End of Life. Bond wire change only. Refer to PCN# 201004013F dated August 2, 2010.
SAF7730HV/N332	SAF7730HV/N332,557		935282255557	N	C	3	31-okt-11	31-jan-12	SAF7730HV/N332D	Standard End of Life. Bond wire change only. Refer to PCN# 201004013F dated August 2, 2010.
SAF7730HV/N334	SAF7730HV/N334,518		935282473518	N	C	3	31-okt-11	31-jan-12	SAF7730HV/N334D	Standard End of Life. Bond wire change only. Refer to PCN# 201004013F dated August 2, 2010.
SAF7730HV/N334	SAF7730HV/N334,557		935282473557	N	C	3	31-okt-11	31-jan-12	SAF7730HV/N334D	Standard End of Life. Bond wire change only. Refer to PCN# 201004013F dated August 2, 2010.
SAF7730HV/N336	SAF7730HV/N336518		935282865518	N	S	3	31-okt-11	31-jan-12	SAF7730HV/N336D	Standard End of Life. Bond wire change only. Refer to PCN# 201004013F dated August 2, 2010.
SAF7730HV/N336	SAF7730HV/N336518		935282865557	N	S	3	31-okt-11	31-jan-12	SAF7730HV/N336D	Standard End of Life. Bond wire change only. Refer to PCN# 201004013F dated August 2, 2010.
SAF7730HV/N336/S30	SAF7730HV/N336/S30		935286187518	N	C	3	31-okt-11	31-jan-12	SAF7730HV/N336D/S30	Standard End of Life. Bond wire change only. Refer to PCN# 201004013F dated August 2, 2010.
SAF7730HV/N336/S30	SAF7730HV/N336/S30		935286187557	N	C	3	31-okt-11	31-jan-12	SAF7730HV/N336D/S30	Standard End of Life. Bond wire change only. Refer to PCN# 201004013F dated August 2, 2010.
SAF7730HV/N336/S31	SAF7730HV/N336/S31		935286188518	N	C	3	31-okt-11	31-jan-12	SAF7730HV/N336D/S31	Standard End of Life. Bond wire change only. Refer to PCN# 201004013F dated August 2, 2010.
SAF7730HV/N336/S31	SAF7730HV/N336/S31		935286188557	N	C	3	31-okt-11	31-jan-12	SAF7730HV/N336D/S31	Standard End of Life. Bond wire change only. Refer to PCN# 201004013F dated August 2, 2010.
SAF7730HV/N336/S32	SAF7730HV/N336/S32		935289216557	N	C	3	31-okt-11	31-jan-12	SAF7730HV/N336D/S32	Standard End of Life. Bond wire change only. Refer to PCN# 201004013F dated August 2, 2010.
SAF7730HV/N366	SAF7730HV/N366,518		935280686518	N	C	3	31-okt-11	31-jan-12	SAF7730HV/N366D	Standard End of Life. Bond wire change only. Refer to PCN# 201004013F dated August 2, 2010.
SAF7730HV/N366	SAF7730HV/N366,557		935280686557	N	C	3	31-okt-11	31-jan-12	SAF7730HV/N366D	Standard End of Life. Bond wire change only. Refer to PCN# 201004013F dated August 2, 2010.
TDA7073AT/N4	TDA7073AT/N4112	Dual BTL power driver	935262848112	T	M	3	31-jul-11	31-jan-12	None Noted	Standard End of Life. Contact your local NXP sales office.
TDA7073AT/N4	TDA7073AT/N4112	Dual BTL power driver	935262848118	T	M	3	31-jul-11	31-jan-12	None Noted	Standard End of Life. Contact your local NXP sales office.
TDA8588AJ/N2/R1	TDA8588AJ/N2/R1,11	IPAS2	935275488112	T	C	2	30-sep-11	31-dec-11	TDF8556AJ/N5	Limited Availability. FAB ICN5 Closure.
TDA8588BJ/N2/R1	TDA8588BJ/N2/R1,11	IPAS2	935275489112	T	C	2	30-sep-11	31-dec-11	TDF8556AJ/N5	Limited Availability. FAB ICN5 Closure.
TDA8588J/N2/R1	TDA8588J/N2/R1,112	IPAS2	935275487112	T	M	2	31-mrt-11	30-jun-11	TDF8556J/N4	Limited Availability. FAB ICN5 Closure.
TDA8589AJ/N2/R1	TDA8589AJ/N2/R1,11	IPAS2	935286534112	T	C	2	30-sep-11	31-dec-11	TDF8554AJ/N5	Limited Availability. FAB ICN5 Closure.
TDA8589BJ/N2/R1	TDA8589BJ/N2/R1,11	IPAS2	935275668112	T	C	2	30-sep-11	31-dec-11	TDF8554AJ/N5	Limited Availability. FAB ICN5 Closure.
TDA8589J/N2/R1	TDA8589J/N2/R1,112	IPAS2	935284413112	T	M	2	31-mrt-11	30-jun-11	TDF8554J/N4	Limited Availability. FAB ICN5 Closure.
TJA1021T/20	TJA1021T/20,112		935284351112	N	S	1	31-jan-11	31-jan-11	TJA1021T/20/C	Non-Manufacturable.
TJA1021T/20	TJA1021T/20,118		935284351118	N	S	2	31-mrt-11	31-dec-11	TJA1021T/20/C	Limited Availability. Boeblingen bridgestock being depleted.